NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2587

Customer: PRICON MICROELECTRONICS INC Date: 07 / 08 / 20

Model: NEX50-5E Machine no. 3A Mfg. yy/mm: 2012 . 01

Serial Number: H005110984K1 Gts.: 6880058

Controller: TACT M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

ABNORMAL SOUND AT INJECTION UNIT

Action Taken

> CONDUCT HEAT-UP
> CONDUCT SCREW FWD AND BWD, BUT DURING BWD ABNORMAL SOUND AND VIBRATION HAPPEN
> CONDUCT AUTO PURGING, FOUND OUT "PURGE V" SET ON 100mm/s CHANGE TO 30mm/s
> TRIAL WITH MOLD AND PRODUCT
> 30% SPEED okay BUT 100% NO good as per customer
> NISSEI Observe 100% still okay / can WE to customer
WE WILL CHECK TO OFFICE IF INJ. BALL SCREW TIE BAR CAN ADJUST

SERVICE BY:

1 R. BANTON 3
2 F. CHING 4

TIME:

Start	End
10 : 30	12 : 00

Total: 1 hrs. 30 mins.

Service Fee: Php 4,000.00

J. ALJHON
Authorized Customer Name & Signature

Recommendation/Parts for Quotation