NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 2846

Customer: PRICON MICRO ELECTRONICS, INC. Date: 12 / 07 / 20

Model: UH1000-80 Machine no. 14 Mfg. yy/mm: 1996. 9

Serial Number: P08R010 Gts.: 6197941

Controller: 93T M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem	
	FE80S12H
	P08Q011
INSTALLATION OF NEW BLADDER	N93C
(RUBBER BUSH SET)	1995. 9
	m/c NO. 16

Action Taken

> INSTALL NEW BLADDER (2 MACHINE)
- RUBBER BUSH SET
> INSTALL NITROGEN 90 MPA ONLY (M/C NO. 14) AND THE OTHER MACHINE (M/C NO. 16) ONLY 50 MPA, FOR INSTALLATION AGAIN OF NITROGEN, WILL WAIT FOR CUSTOMER SPARE
>

SERVICE BY:

1 X. RAMIREZ 3 _____

2 F. CHING 4 _____

TIME:

Start	End
10 : 30	14 : 30

Total: 3 hrs. 30 mins.

LEANNE TAMANNAL
Authorized Customer Name & Signature

Service Fee: Php 31,600.00

Recommendation/Parts for Quotation

** NOTE:
> SERVICE FEE TOTAL = #16,000
OF (2) FWU M/C
> AIR FREIGHT COST = 15,000
OF TOOLS FROM
JAPAN

PHP 31,000