NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax No: (049)544-5647

SERVICE REPORT

No.: A 3107

Customer: PRICON MICROELECTRONICS, INC.

Date: 04 / 13 / 21

Model: NH 1000-80 (12H) Machine no. 13

Mfg. yy/mm: 1996/9

Serial Number: P08 R009

Gts.: 9197211

Controller: 93+

M/C Service Requested By: SIR ALJHON

Reason for Service / Machine Problem

- CONTINUATION OF TROUBLE SHOOTING.
- CANNOT REACH INJECTION FORWARD PRESSURE (RESIN PRESS).
- ABNORMAL CONTROL OF MOLD HEATER.

Action Taken

- FOUND BACK SCREEN DATA FOR MOLD HEATER CONTROL WAS ADJUSTED
- RETURN ORIGINAL DATA FOR MOLD HEATER CONTROL OK.
- CALIBRATED RESIN PRESSURE
- PARAMETER ADJUST FOR PURGING.
- TEST RUN WITH PRODUCT OK.

ENCOUNTERED DOUBLE INJECTION DURING RUNNING

- FOR MONITORING.

SERVICE BY:

1 @ J RUBIO 3

2 N. NISHIZAWA 4

✓ Henry Guzman
Authorized Customer Name & Signature

TIME:

Start	End
14 :00	17 : 50

Total: 3 hrs. 50 mins.

Service Fee: Php 11,000.00

Recommendation/Parts for Quotation

TOTAL SERVICE FEE.