NISSEI

NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A3690

Customer: PRICON MICRO ELECTRONICS INC. **Date:** 05 / 04 / 22

Model: PN40-5H **Machine no.** 6A **Mfg. yy/mm:** 2004.09

Serial Number: P042011 **Gts.:** 1155343

Controller: NC9300T **M/C Service Requested By:** SIR VINCE

Reason for Service / Machine Problem	
SERVO VALVE REPLACEMENT (2 m/c's) (MATERIAL DROOLING)	PN40-5H P042009 NC9300T 2004.09

Action Taken

- UNINSTALLED OLD SERVO VALVE
- INSTALLED NEW SPARE
- CHECKED FUNCTIONS
- CHECKED IF HAVE OIL LEAK
- MACHINE CAN BE USE
- FOR MONITORING OF HIGH TEMP OF OIL FOR M/C 6A

SERVICE BY:

1 F. CHING 3 K. PADILLA

2 R. BANTON 4

E. Valenzuela

Authorized Customer Name & Signature

TIME:

Start	End
13 : 00	15 : 00

Total: 2 hrs. – mins.

Service Fee: PHP/JPY/USD 10,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐