NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A3805

Customer: PRICON MICRO ELECTRONICS **Date:** 04 / 21 / 22

Model: FE80S12H **Machine no.** 15 **Mfg. yy/mm:** 1995.9

Serial Number: P08P009 **Gts.:** 2319475

Controller: N93C **M/C Service Requested By:** SIR VINCE

Reason for Service / Machine Problem

- S1235: @ SEQUENCE ERROR
- REPLACEMENT OF POWER SUPPLY (5V) AND FAN MOTOR.
- SUCTION HOSE REPLACEMENT DUE TO OIL LEAK.

Action Taken

- REPLACED POWER SUPPLY AND FAN MOTOR.
- REPLACED DASACOM BOARD, SEQUENCE ALARM CLEARED.
- REPLACED SUCTION HOSE, NO OIL LEAK AFTER REPLACEMENT.
- ~~@~~ CONDUCTED OIL REFILL BY CUSTOMER.
- FOR MACHINE FUNCTION AFTER 24 HRS DUE TO BUBBLES ON HYDRAULIC OIL

SERVICE BY:

1 J. RUBIO 3 _____

2 _____ 4 _____

TIME:

Start	End
11 : 30	15 : 00

Total: 3 hrs. mins.

VINCE GALINGGANO
Authorized Customer Name & Signature

Service Fee: PHP/JPY/USD 24,000.00 Q

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐

TOTAL SERVICE FEE