NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4284

Customer: PRICOM MICROELECTRONICS, INC. Date: 11 / 17 / 22

Model: PNC0-5AN Machine no. 21A Mfg. yy/mm: 2010.11

Serial Number: E0061 D0012 K1 Gts.: 6479273

Controller: TACT M/C Service Requested By: SIR VINCE

Reason for Service / Machine Problem

↳ DA201: ORIGIN CORRECTION ~~ERR~~ IS NO COMPLETED.

Action Taken

↳ RECONNECT J111 ~~CONNECTOR~~ CONNECTOR AT SERVO BOARD.
↳ CALIBRATED SCREW POSITION ok.
↳ ADJUSTED LS102 SENSOR.
↳ RETIGHTEN SCREWS OF SCREW POSITION ENCODER.
↳ FOUND OIL CONTAMINATION ON SERVO BOARD.

SERVICE BY:

1 J. RUBIO 3 _____
2 N. NISHIZAWA 4 _____

TIME:

Start	End
13 : 40	15 : 00

Total: 1 hrs. 20 mins.

VINCE CRUZ CANA
Authorized Customer Name & Signature

Service Fee: PHP/JPY/USD 10,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐

TOTAL SERVICE FEE FOR 2 DAYS

↳ SERVO BOARD.
↳ SCREW POSITION ENCODER.
(PD1A) SCALE
→ 0352 J0812-00
SL331-20 SONY
SCREW POS.