NISSEI

NISSEI PLASTIC PHILIPPINES, INC.

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4436

Customer: PRICON MICROELECTRONICS INC. **Date:** 02 / 10 / 23

Model: UH1000 -80 **Machine no.** 13 **Mfg. yy/mm:** 1996.9

Serial Number: P082009 **Gts.:** 9435 296

Controller: 93T **M/C Service Requested By:** SIR VINCE/RAFFY

Reason for Service / Machine Problem

↳ OIL LEAK REPAIR CONTINUATION

Action Taken

↳ REPLACED MAGNETIC CONTACTOR (MC-D)
↳ REPLACED COOLING FAN FOR PC BOARD (2PCS)
↳ REPLACED OIL CLEANER.
↳ BORROWED PUMP AMPLIFIER AT M/C 14
↳ CHECKED ALL FUNCTIONS OK
↳ CONDUCTED AIR ~~REA~~ RELEASE/BLEEDING AT CLAMPING.
↳ NO OIL LEAK ON EJECTOR, CLAMPING AND INJECTION CARRIAGE

SERVICE BY:

1 J. RUBIO 3 _____

2 _____ 4 _____

TIME:

Start	End
14 : 30	18 : 00

RAFY D. ANDAYA
Authorized Customer Name & Signature

Total: 3 hrs. 30 mins.

Service Fee: PHP/JPY/USD 21,000.00

Recommendation/Parts for Quotation

Inclusive of Tax: ☐ Exclusive of Tax: ☐