NISSEI

Unit 11, Building B, Laguna Technopark Standard Factory Building 2, Phase 7
Laguna Technopark- SEZ, Biñan, Laguna Tel. No.: (049)544-5670 Fax: (049)544-5647

SERVICE REPORT

No.: A4568

Customer: PHCON MICROELECTRONICS INC Date: 03/24/23

Model: PN60-5AN Machine no. 21A Mfg. Yy/mm: 2010.11

Serial Number: E0061000181 Gts.: 6575689

Controller: TACT M/C Service Requested By: SIR VINCE

Reason for Service / Machine Problem

PARTS REPLACEMENT ON MACHINE

Action Taken

1) CONDUCTED REPLACEMENT OF AXIS BOARD
2) CONDUCTED REPLACEMENT OF LINEAR SCALE
3) CONDUCTED REPLACEMENT OF PACKING SET FOR INJ CARRIAGE (OPERATIONAL & NON OPERATIONAL)
4) CHECKED FUNCTION, PLAY
- NO OIL LEAK
- SCREWS POSITION WE CAN ZERO RESET

NOTE UPON CERTAIN MACHINE HAVE ALARM "MAIN CPU BOARD BATTERY DOWN", NISSEI RECOMMEND TO CHANGE/REPLACE NEW CPU BOARD (MAIN CPU BOARD)
- ALSO FOUND BROKEN HEATER (FRONT) FOR REPLACEMENT

SERVICE BY:
1 T. CHUA 3
2 I. RAPID 4

TIME:

Start	End
14 : 00	18 : 00

Total: 4 hrs. - mins.

Authorized Customer Name & Signature

Service Fee: PHP/JPY/USD 21,000.00

Recommended Parts for Quotation Inclusive of Tax: ☐ Exclusive of Tax: ☐

1) MAIN CPU BOARD (FOR RESPONSE OF QUOTATION)
2) FRONT BAND HEATER

SERVICE FEE & PARTS QUOTATION