Diagnosa perbaikan Power Supply timbangan WIM, masalah ditemukan di Kapasitor (400V 225J) dan Tiny Trafo (t6012bs)



