Network Project Using Cisco Packet Tracer

Name: Prince Atinyo




Figure 1: This figure displays an image of the completed Network Topology for TechNova Ltd in Cisco Packet Tracer.




Figure 2: This diagram displays the TechNova Ltd Systems server which is located in the IT Department.




Figure 3: This screenshot displays the IP Address configuration for the IT Department




Figure 4: This image displays the IP Address configuration for the Sales Department




Figure 5: This illustration displays the IP Address configuration for the HR Department




Figure 6: This figure displays the FTP configuration for the Server




Figure 7: This image displays IP Configurations for the Server




Figure 8: This figure displays the confirmation of IP address in Command Prompt




Figure 9: This image displays the assigning of the IT Department's IP Address automatically using the DHCP Server




Figure 10: This figure displays IP Address verification by using the command line “ipconfig” which returns the correct IP Address and also displays the Ping Verification (4 packets, 4 received, 0 lost).




Figure 11: This figure displays the connection from the switch in the IT Department to the router




Figure 12: This figure displays the connection from the switch in the Sales Department to the router




Figure 13: This figure displays the connection from the switch in the HR Department to the router




Figure 14: IP Helper address is used to configure the DHCP on the Sales and HR switches




Figure 15: This figure displays the connection between the IT Department and the Sales Department. One of the packets from the ping from the Sales to the IT Department failed.




Figure 16: This image displays a successful ping from a HR PC to an IT PC




Figure 17: This image displays the Access Control List (ACL) applied on the router so the Sales Department (192.198.20.0/24) cannot reach the IT Department (192.168.10.0/24) but still access the server services while all other traffic remains allowed.




Figure 18: This screenshot shows the ping test from the Sales Department to the IT Department which comes back as “Destination Host unreachable”, meaning the ACL has been applied successfully.




Figure 19: This diagram displays a successful ping from the Sales Department to the HR Department further proving the ACL enabled only applies to the IT Department and not all departments.




Figure 20: This screenshot displays the Sales Department having access to the http service on the server