

GENERAL NOTES: CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY. 48'-0" OUT-TO-OUT OF STEEL I RF1-1 EC-1 EC-6SIDEWALL FRAMING: FRAME LINE E 3 C\_CAP SIDEWALL SHEETING & TRIM: FRAME LINE E PANELS: 26 Ga. PBR — Covert Green

MEMBER TABLE
FRAME LINE E

MARK PART LENGTH

E-3 E1045\_12 23'-11 3/4"


E-4 E1045\_12 23'-11 3/4"








L ABILITY CENTER
ILITY WAY
TY, UT 84060
ABILITY CENTER STORAGE



DESIGN: ML DRAFT: CC CHECK: DATE: 10/ 6/20

20082740

6 11 REV O



BOLT TABLE
FRAME LINE 1
LOCATION QUAN TYPE DIA LENGTH
Columns/Raf 4 A325 1/2" 1 1/4"

MEMBER		
FRAME I	INE 1	
MARK	PART	LENGTH
EC-1	08B12	6 1/16"
EC-2	c825_14	7'-10 3/16"
EC-3	c825_14	10'-0 11/16"
EC-4	c825_14	15'-10 5/16"
ER-1	08B14	25'-11 1/4"
G-1	z825_16	8'-2,1/2"
G-2	z825_16	5'-2"
CB-1	0.25_CBL	11'-2 7/16"
CB-2	0.25_CBL	9'-7 3/4"

CONNECTION PLATES
FRAME LINE 1
DID MARK/PART
1 BCC3/5
2 PBC3N
3 GC35
4 GEB

BUILDING SYSTEMS INC.





STORAGE


L ABILITY CENTER ILITY WAY TY, UT 84060



DESIGN: ML
DRAFT: CC
CHECK:
DATE: 10/6/20

<sup>JOB #</sup> 20082740

SHEET 7 OF 11 REV



BOLT TABLE
FRAME LINE 3
LOCATION QUAN TYPE DIA LENGTH
Columns/Raf 4 A325 1/2" 1 1/4"

MEMBER TABLE
FRAME LINE 3

MARK PART LENGTH

EC-2 c825\_14 7'-10 3/16"
EC-4 c825\_14 15'-10 5/16"
EC-5 c825\_14 10'-1 3/16"
EC-6 08B12 6 1/16"
ER-2 08B14 25'-11 1/4"
G-3 z825\_16 5'-0"
G-4 z825\_16 8'-4 1/2"
CB-3 0.25\_CBL 9'-9 1/4"
CB-4 0.25\_CBL 11'-4 1/4"

CONNECTION PLATES
FRAME LINE 3
DID MARK/PART
1 BCC3/5
2 PBC3N
3 GC35
4 GEB

BUILDING SYSTEMS INC.





ACCREDITED
Metal Building Systems
AC 472

STORAGE

NATIONAL

NATIONAL ABILITY CENTER 1000 ABILITY WAY PARK CITY, UT 84060



DESIGN: ML DRAFT: CC CHECK: DATE: 10/6/20

JOB # 20082740

SHEET OF REV