









LYOOL PRAMING		DAVID MOLCHKING	7940 ST JOSEPH ST		COANDALE, NV 00040	DAVID HOLCHRIND
REVISIONS	REV DATE: DESCRIPTION					
	REV	\triangleleft	\triangleleft	\triangleleft	4	\$ ₩



DESIGN: ML DRAFT: BS CHECK: DATE: 1/27/21

20113820

4 11 REV



MEMBER	TABLE	
FRAME I	lne a	
MARK	PART	LENGTH
DJ-2	c825_16	15'-3 3/4"
DH-2	c825_16	11'-10"
E-1	E845_14	19'-11 3/4"
E-2	E845_14	19'-11 1/2"
E-3	E845_14	19'-11 3'/4"
G-6	Z825_16	3'-9 1/4"
G-7	Z825_16	7'-6 1/2"
G-8	Z825_16	23'-9 1/4"
CB-2	0.25 CBL	22'-6 1/2"
CB-3	0.25 CBL	22'-7 1/2"

CONNECTION PLATES
FRAME LINE A
DID MARK/PART


1 PBC3N
2 EJ1L
3 GC35
4 EJ1R
5 BCC8







SIDEWALL FRAMING	DAVID HOTCHKISS 2940 ST. JOSEPH ST. LOGANDALE, NV 89040	DAVID HOTCHKISS	
------------------	---	-----------------	--



DESIGN: ML DRAFT: BS CHECK: DATE: 1/27/21

20113820

5 of 11 REV (

GENERAL NOTES:

CO BUILDING SYSTEMS RECOMMENDS THAT AT LEAST ONE BRACED BAY BE INSTALLED PRIOR TO OTHER FRAME LINES. THIS INCLUDES EAVE STRUTS, PURLIN STRUTS, WIND BENTS, AND BRACE CABLE/ROD OVER THE COMPLETE BAY. FAILURE TO DO SO MAY RESULT IN SERIOUS DAMAGE TO THE STRUCTURE AND/OR BODILY INJURY.

MEMBER TABLE
FRAME LINE D

MARK PART LENGTH

E-3 E845_14 19'-11 3/4"
E-4 E845_14 19'-11 3/4"
E-5 E845_14 19'-11 1/2"
G-9 Z825_16 21'-1 1/2"
G-10 Z825_16 22'-3"
G-11 Z825_16 21'-1 1/2"
CB-4 0.25_CBL 23'-3 1/4"


CONNECTION PLATES
FRAME LINE D
DID MARK/PART
1 GC35

BUILDING SYSTEMS INC.






REVISIONS
SIDEWALL FRAMING
DAVID HOTCHKISS
2940 ST. JOSEPH ST.
LOGANDALE, NV 89040
DAVID HOTCHKISS





DESIGN: ML DRAFT: BS CHECK: FL DATE: 1/27/21

20113820

6 11 REV













HOTCHKISS ST. JOSEPH ST. IDALE, NV 89040

DAVID H 2940 ST LOGANDA VISIONS



DESIGN: ML DRAFT: BS CHECK: £4 DATE: 1/27/21

