## SOH - ADMIN & IPD

## ELALAN - RFI NO. 2



<u>S/N</u>	DESCRIPTION	ELALAN'S COMMENT	CONSULTANT'S RESPONSE
1	Submission of Tender	Kindly confirm tender submission date.	
2	Site Visit	Site visit is required for better understanding of work scope. Kindly confirm when we can visit the site.	
	ADMIN BUILDING		
3	Modification/Correction of existing structural defects-(Item D. Page 2)	BOQ detail is very scanty. Kindly provide detailed description, drawings, pictures, etc. indicating the detail of work.	
4	Refurbish, rehabilitate and making good existing spiral staircases of Tread tapering 1200mm wide (28nr), with steel railing of 26m long including epoxy finishes - (Item N. Page 2)	Drawings and other details of the stair is required	
	SKY BRIDGE		
5	Fabricate and Install external diagonal steel panel trusses of (36 Panels) with support including all necessary bolts, accessories & fittings with attached 12mm tempered/toughened glasses (measured separately) - (Item A. Page 19)	Kindly avail us with Structural designs/details of the sky bridge.	
6	Fabricate GRP Seat overall size 1550mm x 4400mm including all necessary accessories and making good with mosaic tiles	Please clarify what this item of work is/supply a detailed design.	
7	Construct Concrete Platform (auditorium) & finishings of size 14000x2400mm including 2 steps of 2nr.	what is the depth of the concrete platform and what kind of finishing is expected on it?	

## SOH - ADMIN & IPD

## ELALAN - RFI NO. 2



S/N	DESCRIPTION	ELALAN'S COMMENT	CONSULTANT'S RESPONSE
8	Structural Drawings	Kindly provide us with Structural Drawings for this project.	
	MEP WORKS		
9	PANELS AND DISTRIBUTION BOARDS	Could you please provide us with the schematic drawings for the Panel Boards, TV/Telephone panels (PABX) and Distribution Boards?	
10	LIGHT FITTINGS	Could you please provide us with the Lighting Legends/Datasheets?	
11	CABLES	Could you please clarify if the cable should be PVC/SWA/PVC OR PVC/PVC cable?	
12	We have noticed that this is an existing building	What is our exact scope of works, the BOQ's received are incomplete and will not offer a commissioned system.  Please provide us with the detailed MEP drawings of this project for review	