Assembly Field Values

Machine Code

sw t2, -6(s3) sw x7, -6(x19) sh s4, 23(t0) sh x20,23(x5) sb t5, 0x2D(zero) sb x30,0x2D(x0)

	imm _{11:5}	rs2	rs1	funct3	imm _{4:0}	ор
	1111 111	7	19	2	11010	35
	0000 0000	20	5	1	10111	35
)	0000 001	30	0	0	01101	35
	7 bits	5 bits	5 bits	3 bits	5 bits	7 bits

	imm _{11:5}	rs2	rs1	funct3	imm _{4:0}	
	1111 111	00111	10011	010	11010	01
	0000 000	10100	00101	001	10111	01
	0000 001	11110	00000	000	01101	01
_	7 bits	5 bits	5 bits	3 bits	5 bits	

imm _{4:0}	ор	
11010	010 0011	(0xFE79AD23)
10111	010 0011	(0x01429BA3)
01101	010 0011	(0x03E006A3)
5 bits	7 bits	