


$P_O$  [ $C_r=1480\mu F$ ,  $C_L=630.0\mu F$ , rpm=100] (FWR- $\Delta$ )

Power [mW]



$R_L$  [ $\Omega$ ]

P(FWR1)  
P(FWR2)