

Incident Report — INC-2025-004

Fire Incident | Low Severity

Incident ID	INC-2025-004
Date	2025-10-15
Equipment Tag	200-E-204
Equipment Name	Feed/Effluent Exchanger
Unit	Hydrocracker Unit (200)
Type	Fire Incident
Severity	Low
Investigator	Sunita Patil (Inspection Engineer, EMP-0015)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-10-15, a low severity fire incident was recorded on 200-E-204 (Feed/Effluent Exchanger) in the Hydrocracker Unit. The event was investigated by Sunita Patil (Inspection Engineer, EMP-0015).

2. Root Cause

Investigation determined the probable root cause to be relief valve set-point drift. Contributing factors were reviewed against the governing procedure SOP-200-006 and safety procedure SP-004.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.