

Incident Report — INC-2025-008

Vibration Trip | High Severity

Incident ID	INC-2025-008
Date	2025-09-04
Equipment Tag	500-V-506
Equipment Name	Equalization Tank
Unit	Effluent Treatment Plant (500)
Type	Vibration Trip
Severity	High
Investigator	Sunita Patil (Inspection Engineer, EMP-0015)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-09-04, a high severity vibration trip was recorded on 500-V-506 (Equalization Tank) in the Effluent Treatment Plant. The event was investigated by Sunita Patil (Inspection Engineer, EMP-0015).

2. Root Cause

Investigation determined the probable root cause to be mechanical seal wear beyond service life. Contributing factors were reviewed against the governing procedure SOP-500-013 and safety procedure SP-006.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.