

Incident Report — INC-2026-003

Seal Failure | Medium Severity

Incident ID	INC-2026-003
Date	2026-05-15
Equipment Tag	300-CT-304
Equipment Name	Induced Draft Cooling Tower
Unit	Utilities & Offsites (300)
Type	Seal Failure
Severity	Medium
Investigator	Pooja Rao (HSE Officer, EMP-0036)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2026-05-15, a medium severity seal failure was recorded on 300-CT-304 (Induced Draft Cooling Tower) in the Utilities & Offsites. The event was investigated by Pooja Rao (HSE Officer, EMP-0036).

2. Root Cause

Investigation determined the probable root cause to be inadequate lockout-tagout verification prior to maintenance. Contributing factors were reviewed against the governing procedure SOP-300-009 and safety procedure SP-005.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.