

Inspection Report — 400-T-404

Corrosion Mapping | 2025-05-05

Report ID	IR-400-T-404-2025-035
Equipment Tag	400-T-404
Equipment Name	LPG Bullet
Unit	Tank Farm / Storage (400)
Inspection Date	2025-05-05
Inspection Type	Corrosion Mapping
Inspector	Shalini Naik (Inspection Engineer, EMP-0014)
Next Due Date	2026-05-05
Governing SOP	SOP-400-012

1. Scope

Risk-Based Inspection (RBI) assessment of 400-T-404 performed by Shalini Naik (Inspection Engineer, EMP-0014) in accordance with SOP-400-012 and OISD inspection guidelines.

2. Findings

During Corrosion Mapping inspection of 400-T-404 (LPG Bullet) conducted on 2025-05-05, the inspector identified a moderate severity defect: thickness loss approaching but not below minimum retirement thickness. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2026-05-05.

3. Recommendation

Recommend monitoring at next scheduled interval and update of the risk-based inspection interval for 400-T-404 accordingly.