

Incident Report — INC-2024-014

Seal Failure | Low Severity

Incident ID	INC-2024-014
Date	2024-05-15
Equipment Tag	500-V-510
Equipment Name	Sludge Thickener
Unit	Effluent Treatment Plant (500)
Type	Seal Failure
Severity	Low
Investigator	Pooja Bhosale (Inspection Engineer, EMP-0017)
Regulatory Reportable	No
Follow-up Work Order	WO-2024-0017

1. Incident Summary

On 2024-05-15, a low severity seal failure was recorded on 500-V-510 (Sludge Thickener) in the Effluent Treatment Plant. The event was investigated by Pooja Bhosale (Inspection Engineer, EMP-0017).

2. Root Cause

Investigation determined the probable root cause to be instrumentation drift causing delayed alarm response. Contributing factors were reviewed against the governing procedure SOP-500-014 and safety procedure SP-002.

3. Corrective Actions

A follow-up work order WO-2024-0017 was raised to address the immediate equipment condition. This event did not meet the threshold for external regulatory reporting.