

Incident Report — INC-2025-001

Vibration Trip | Low Severity

Incident ID	INC-2025-001
Date	2025-02-26
Equipment Tag	300-BLR-301
Equipment Name	Package Boiler
Unit	Utilities & Offsites (300)
Type	Vibration Trip
Severity	Low
Investigator	Sunita Patil (Inspection Engineer, EMP-0015)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-02-26, a low severity vibration trip was recorded on 300-BLR-301 (Package Boiler) in the Utilities & Offsites. The event was investigated by Sunita Patil (Inspection Engineer, EMP-0015).

2. Root Cause

Investigation determined the probable root cause to be process upset from upstream unit. Contributing factors were reviewed against the governing procedure SOP-300-009 and safety procedure SP-010.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.