

Incident Report — INC-2025-009

Minor Leak | Low Severity

Incident ID	INC-2025-009
Date	2025-10-17
Equipment Tag	200-F-206
Equipment Name	Reactor Feed Heater
Unit	Hydrocracker Unit (200)
Type	Minor Leak
Severity	Low
Investigator	Sunil Naik (HSE Officer, EMP-0034)
Regulatory Reportable	No
Follow-up Work Order	None issued

1. Incident Summary

On 2025-10-17, a low severity minor leak was recorded on 200-F-206 (Reactor Feed Heater) in the Hydrocracker Unit. The event was investigated by Sunil Naik (HSE Officer, EMP-0034).

2. Root Cause

Investigation determined the probable root cause to be operator deviation from startup SOP sequence. Contributing factors were reviewed against the governing procedure SOP-200-006 and safety procedure SP-004.

3. Corrective Actions

No immediate corrective work order was required; findings were logged for trend monitoring. This event did not meet the threshold for external regulatory reporting.