

Inspection Report — 100-P-101

Ultrasonic Thickness | 2024-04-20

Report ID	IR-100-P-101-2024-029
Equipment Tag	100-P-101
Equipment Name	Centrifugal Pump
Unit	Crude Distillation Unit (100)
Inspection Date	2024-04-20
Inspection Type	Ultrasonic Thickness
Inspector	Shalini Naik (Inspection Engineer, EMP-0014)
Next Due Date	2025-04-20
Governing SOP	SOP-100-001

1. Scope

Risk-Based Inspection (RBI) assessment of 100-P-101 performed by Shalini Naik (Inspection Engineer, EMP-0014) in accordance with SOP-100-001 and OISD inspection guidelines.

2. Findings

During Ultrasonic Thickness inspection of 100-P-101 (Centrifugal Pump) conducted on 2024-04-20, the inspector identified a major severity defect: crack indication detected during UT scan, immediate follow-up required. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2025-04-20.

3. Recommendation

Recommend immediate corrective work order and update of the risk-based inspection interval for 100-P-101 accordingly.