

Inspection Report — 200-PSV-207

External Visual | 2025-04-01

Report ID	IR-200-PSV-207-2025-036
Equipment Tag	200-PSV-207
Equipment Name	Reactor Relief Valve
Unit	Hydrocracker Unit (200)
Inspection Date	2025-04-01
Inspection Type	External Visual
Inspector	Shalini Naik (Inspection Engineer, EMP-0014)
Next Due Date	2025-09-28
Governing SOP	SOP-200-006

1. Scope

Risk-Based Inspection (RBI) assessment of 200-PSV-207 performed by Shalini Naik (Inspection Engineer, EMP-0014) in accordance with SOP-200-006 and OISD inspection guidelines.

2. Findings

During External Visual inspection of 200-PSV-207 (Reactor Relief Valve) conducted on 2025-04-01, the inspector identified a major severity defect: crack indication detected during UT scan, immediate follow-up required. This finding has been logged against the equipment's RBI history and a follow-up inspection is scheduled for 2025-09-28.

3. Recommendation

Recommend immediate corrective work order and update of the risk-based inspection interval for 200-PSV-207 accordingly.