



Operations/Work/Job Activity covered by this assessment: Final-Inspection

Required Personal Protective Equipment (PPE) :



Safety glasses must be worn at times.



Long and loose hair must be contained.



Appropriate footwear with substantial uppers must be worn.



Close fitting/protective clothing to cover arms and legs must be worn.



Respiratory protection devices required.



Oil free leather gloves and spats must be worn.



Hearing protection must be used when using this machine.

Loading & Unloading Check:

- 1. Ensure no slip/trip is present in work pass and walk ways.**
- 2. Ensure that work area is clean and clear of grease, oil and any flammable materials.**
- 3. Refer Work Instructions PSP/WI/14 while handling.**
- 4. Refer VT Procedure PSP/PM/22 While Visual Inspection.**

Operations Procedure:

Scope: To check whether the Component coated and finished as per customer requirements.

1. Take out print of FIR (Final-Inspection Report) format No. QF/QA/11 from software.
2. FIR indicates the Customer Name, Part Name, Qty etc...
3. Carry out Visual Inspection Document No. QF/QMS/00/26 to check scratch, dents, pinholes etc., Checking & Recording the dimension, coating length and total length of the job.
4. Dimension to check using Calibrated Instruments like, Vernier Calipers and Micrometers. Always check for error and mention instrument no. on FIR.
5. Compare the component with Pre-inspection Report/ Drawing given by the Customer.
6. Fill the before coating dimension, after coating dimension, calculate the thickness observed and check for the value required by the customer, also check the surface roughness and enter the value.
7. Record components details like, punch no and mention any remark/observation in the remark cells.
8. If Deviation is found contact your QA/Production Engineer/ Works Manager, and get clearance from the Customer by sending Deviation Report.
9. After getting the Deviation approval from the Customer the Production Engineer/ Works Manager will approve.
10. After approval, the FIR is marked completed and saved in Software.
11. After Final Inspection Send FIR & TC to Customer.

Assessor :		Signature:		Date:	
Approved:		Signature:		Date:	