

PLASMA SPRAY PROCESSORS Works Instruction	QF/QMS/02/14	
	Rev. 01	
	Date : 14/02/2024	

Operations/Work/Job Activity covered by this assessment: Handling Customer Components

Required Personal Protective Equipment (PPE) :



Safety glasses must be worn at times.



Long and loose hair must be contained.



Appropriate footwear with substantial uppers must be worn.



Close fitting/protective clothing to cover arms and legs must be worn.



Respiratory protection devices required.



Oil free leather gloves and spats must be worn.



Hearing protection must be used when using this machine.

Loading & Unloading Check:

1. Ensure no slip/trip is present in work pass and walk ways.
2. Ensure that work area is clean and clear of grease, oil and any flammable materials
3. Ensure that customer components (e.g. rolls, rotors, screws, etc.) is properly tighten by rope during Loading & Unloading.

Operations Procedure:

1. When you receive a component from the customer, see whether the Wooden Box , Protective Packing of the job is intact, if it is damaged or broken; inform the Supervisor/Production Engineer/Works Manager.
2. Ensure the handling equipment such as sling, hooks and hoist are in proper condition.
3. Lift with the help of EOT/ Hydra/ Forklift and place it very carefully at the designated area.
4. While lifting, positioning, placing, ensure the component is properly balanced and slings and wire ropes are properly placed.
5. Ensure the component does not collide with any other component/object to prevent damage or any injury, while positioning/placing.
6. Avoid keeping the component without packing on to the floor or kept on Wooden Plank.
7. Make sure that the component is handled carefully from the time it enters the works till the time of dispatch.
8. Take proper care of the component while packing, lifting, and loading while dispatching.
9. Keep the slings at the designated areas.

Assessor :		Signature:		Date:	
Approved:		Signature:		Date:	