

PLASMA SPRAY PROCESSORS

Works Instruction

QF/QMS/02/29

Rev. 00

Date : 25.11.2023



Operations/Work/Job Activity covered by this assessment: Checking For Moisture in Blasting Gun

Required Personal Protective Equipment (PPE) :



Safety glasses must be worn at times.



Long and loose hair must be contained.



Appropriate footwear with substantial uppers must be worn.



Close fitting/protective clothing to cover arms and legs must be worn.



Respiratory protection devices required.



Oil free leather gloves and spats must be worn.



Hearing protection must be used when using this machine.

Note: Refer W.I of Blasting QF-QMS-02-04 While Blasting.

Operation Procedure:

1. Get a Mirror, rest it on a wall.
2. Hold the Air gun at a distance of 6'' from the mirror.
3. Flow the air Keeping constant distance from the mirror for 3 to 4 mins.
4. Observe the moisture in mirror, if found inform Production/QA/ Maintenance department.

Assessor :

Signature:

Date:

Approved:

Signature:

Date: