S/N #IM1021060034

MODE	SET VALUE	DMM READING	ZIM READING	ERROR	PASS
DC Voltage	10.0000 V	10.0080 V	10.0090 V	0.0010 V	OK
	20.0000 V	20.0040 V	20.0041 V	0.0001 V	OK
	50.0000 V	49.9960 V	49.9945 V	-0.0015 V	OK
	100.0000 V	99.9800 V	99.9814 V	0.0014 V	OK
with 100V range (Gai	n : 0.919499, Offset	: 0.085193)			
DC Voltage	100.000 V	101.190 V	101.203 V	0.0132 V	OK
	200.000 V	202.030 V	202.030 V	0.0005 V	OK
	500.000 V	504.260 V	504.254 V	-0.0059 V	OK
	1,000.000 V	1,008.070 V	1,008.114 V	0.0444 V	OK
	-50.00 'C	-50.00 'C	-49.99 'C	0.01 'C	OK
Temperature	0.00 'C	0.00 'C	-0.02 'C	-0.02 'C	OK
	50.00 'C	50.00 'C	49.98 'C	-0.02 'C	OI
					OK
	100.00 'C	100.00 'C	100.00 'C	0.00 'C	OK OK
with PT100 sensor (Ga			100.00 'C	0.00 'C	
with PT100 sensor (Ga			100.00 'C 1.0 Hz	0.00 'C 0.026%	
with PT100 sensor (Ga	ain : 1.000535, Offse	t : 0.124286)			OK
with PT100 sensor (Ga	nin : 1.000535, Offse	t : 0.124286) 1.00027 Hz	1.0 Hz	0.026%	OK OK
	nin : 1.000535, Offse 1.0 Hz 10.0 Hz	1.00027 Hz 10.00460 Hz	1.0 Hz 10.0 Hz	0.026% 0.046%	OK OK OK

with 100mohm resistor @ 400mA range

Freq (Hz)	Zreal (Ω)	Zimag (Ω)	Zmod (Ω)	Zphase (°)	Pass
10	0.00999097	1.80E-05	0.00999098	0.103	NOK
1	0.00998631	4.89E-06	0.00998631	0.028	OK
0.1	0.00998202	1.06E-05	0.00998202	0.061	OK
with 10mohm resistor (@ 2A range				
	0.0000.120	4 775 05	0.0000.430	2.24	01/
10	0.0999439	1.77E-05	0.0999439	0.01	OK
1	0.0999567	3.07E-06	0.0999567	0.002	OK
0.1	0.099942	1.45E-05	0.099942	0.008	OK
with 100mohm @ 200r	nA range				
	0.007054	7.225.05	0.007054	0.004	01/
10	0.997964	-7.23E-05	0.997964	-0.004	OK
1	0.997906	-7.74E-05	0.997906	-0.004	OK
0.1	0.997947	5.24E-05	0.997947	0.003	OK
with 1ohm @ 20mA rai	nge				
10	9.99652	-0.00231129	9.99652	-0.013	OK
1	9.99655	-0.00139399	9.99655	-0.008	ОК
0.1	9.99604	0.00135273	9.99604	0.008	OK

with 10ohm @ 2mA range