S/N #IM1021060034

MODE	SET VALUE	DMM READING	ZIM READING	ERROR	PASS
DC Voltage	10.0000 V	10.0080 V	10.0090 V	0.0010 V	OK
	20.0000 V	20.0040 V	20.0041 V	0.0001 V	OK
	50.0000 V	49.9960 V	49.9945 V	-0.0015 V	OK
	100.0000 V	99.9800 V	99.9814 V	0.0014 V	OK
rith 100V range (Ga	in: 0.919499, Offset:	0.085193)			
DC Voltage	100.000 V	101.190 V	101.203 V	0.0132 V	OK
	200.000 V	202.030 V	202.030 V	0.0005 V	OK
	500.000 V	504.260 V	504.254 V	-0.0059 V	OK
			4 000 44 4 1 /	0.04441/	\circ
rith 1000V range (G	1,000.000 V Gain: 1.001311, Offset:	1,008.070 V 0.927582)	1,008.114 V	0.0444 V	OK
rith 1000V range (G	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	-49.99 'C	0.0444 V	OK
	Gain: 1.001311, Offset:	0.927582)			
ith 1000V range (G	Gain: 1.001311, Offset: -50.00 'C	0.927582) -50.00 'C	-49.99 'C	0.01 'C	OK
	Gain: 1.001311, Offset: -50.00 'C 0.00 'C	0.927582) -50.00 'C 0.00 'C	-49.99 'C -0.02 'C	0.01 'C -0.02 'C	OK OK
Temperature	-50.00 'C 0.00 'C 50.00 'C	0.927582) -50.00 'C 0.00 'C 50.00 'C 100.00 'C	-49.99 'C -0.02 'C 49.98 'C	0.01 'C -0.02 'C -0.02 'C	OK OK OK
Temperature	-50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C sain: 1.000535, Offset:	0.927582) -50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C	-49.99 'C -0.02 'C 49.98 'C 100.00 'C	0.01 'C -0.02 'C -0.02 'C 0.00 'C	OK OK OK
Temperature rith PT100 sensor (G	-50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C ain: 1.000535, Offset:	0.927582) -50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C	-49.99 'C -0.02 'C 49.98 'C 100.00 'C	0.01 'C -0.02 'C -0.02 'C 0.00 'C	OK OK OK OK
Temperature	-50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C sain: 1.000535, Offset:	0.927582) -50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C	-49.99 'C -0.02 'C 49.98 'C 100.00 'C	0.01 'C -0.02 'C -0.02 'C 0.00 'C	OK OK OK
Temperature rith PT100 sensor (G	-50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C ain: 1.000535, Offset:	0.927582) -50.00 'C 0.00 'C 50.00 'C 100.00 'C 100.00 'C	-49.99 'C -0.02 'C 49.98 'C 100.00 'C	0.01 'C -0.02 'C -0.02 'C 0.00 'C	OK OK OK OK

with 100mohm resistor @ 400mA range

Freq (Hz)	Zreal (Ω)	Zimag (Ω)	Zmod (Ω)	Zphase (°)	Pass
10	0.00999097	1.80E-05	0.00999098	0.103	OK
1	0.00998631	4.89E-06	0.00998631	0.028	OK
0.1	0.00998202	1.06E-05	0.00998202	0.061	OK
with 10mohm resistor (@ 2A range				
10	0.0999439	1.77E-05	0.0999439	0.01	OK
1	0.0999567	3.07E-06	0.0999567	0.002	OK
0.1	0.099942	1.45E-05	0.099942	0.008	OK
with 100mohm @ 200r	mA range				
10	0.997964	-7.23E-05	0.997964	-0.004	OK
1	0.997906	-7.74E-05	0.997906	-0.004	OK
0.1	0.997947	5.24E-05	0.997947	0.003	OK
with 1ohm @ 20mA ra	nge				
10	9.99652	-0.00231129	9.99652	-0.013	OK
1	9.99655	-0.00139399	9.99655	-0.008	OK
0.1	9.99604	0.00135273	9.99604	0.008	OK

with 10ohm @ 2mA range