

INCIDENT REPORT

Controlled demonstration record for local testing

Incident ID	INC-DEMO-2026-002
Classification	Internal - Fictional demonstration
Title	Hydraulic Oil Release and Slip Hazard
Date / time	2026-09-05 16:12
Asset / location	HP-800-03, Hydraulic Press Line 3
Severity	Recordable-potential incident
Reported by	A. Khan, Operator T-1187

This record is fictional and intended to test upload, OCR, evidence retrieval, incident analysis and supervisor review. It does not authorize work or establish a site procedure.

1. Event description

An operator observed hydraulic fluid spraying from the seal area during a controlled jog test after maintenance. Fluid reached the floor near the operator access path. No contact injury was reported, but the area became a slip and exposure hazard.

2. Immediate actions

Stop the jog test; apply LOTO; restrict access; use the spill kit; report the release; inspect pressure readings and preserve the failed seal for examination.

3. Recorded evidence

Vibration at bearing B2 was recorded at 5.6 mm/s RMS. Accumulator pressure was 171 bar. Seal #4 showed an active leak. Maintenance log entries show worsening vibration and seal condition over three weeks.

4. Proposed follow-up

Keep the press isolated until the authorized maintenance supervisor confirms depressurization; replace the seal using the approved procedure; verify guards and housekeeping; perform a documented restart check.

5. Review fields

Supervisor disposition: _____ Date: _____

Safety review required: Yes / No Work authorization required: Yes / No

Source documents attached: Yes / No Evidence verified: Yes / No