




MOSFET_driver

File: untitled.kicad_sch

File: Sensors_Telemetry.kicad_sch

File: connector_signals.kicad_sch

File: Voltage_conv_prot.kicad_sch

TP1 12V_TP

TP2 GND_TP

TP3 5.2V_TP

D1 LED

D2 LED

D3 LED

R4 R_US

R5 R_US


R6 R_US

3.3V


Sheet: /
File: X19-Control-Board.kicad_sch

Size: A4	Date:
KiCad E.D.A. 10.0.5—unknown	

Rev:
Id: 1/5



Sheet: /MOSFET_driver/ File: untitled.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.5-unknown	Id: 2/5	



Fade or keep RPP

12V


R29
100k

D14
?????????

Q11
AO3400A

The image shows two circuit diagrams for the INA237AIDGSR sensor (U5 and U6). Both sensors are connected to a 3.3V supply via a pull-up resistor (R31 for U5, R33 for U6) and a 10k resistor. The I2C lines (SDA and SCL) are connected to the module. The sensors are also connected to a 12V supply via a 120mΩ resistor (R30 for U5, R32 for U6). The output of the sensors is connected to a 5.2V_pre_sense (U5) or 12V_pre_sense (U6) signal.

Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 10.0.5—unknown		Id: 6/5



THIS PINOUT IS NOT FINAL

I'm down to add a bigger ST-Link one, but we need to know v2, v3, etc

Break Out SWD

nRST

1

2

SWCLK

3

SWDIO

4

3.3V

5

J6

Conn_01x05

Mega Connector/Breakout (if we have space)

nRST

1

GATE1

2

GATE2

3

GATE3

4

GATE4

5

MOSI

6

SCLK

7

MISO

8

GATE5

9

GATE6

10

GATE7

11

GATE8

12

GATE9

13

GATE10

14

STM_TO_INPUT_CAN

15

STM_TO_OUTPUT_CAN

16

32

31

30

29

28

27

26

25

24

23

22

21

20

19

18

17

PWM_A1

PWM_A2

PWM_B1

PWM_B2

PWM_C1

PWM_C2

PWM_D1

PWM_D2

SWCLK

SWDIO

SDA

SCL

CS_BMI

nINT_BN0

RST_BN0

INT1_BMI

NOT USED

USB C 2.0 (Want to do it, but is useless here)

P1

USB_C_Plug_USB2.0

VBUS

A4

CC

A5

VCONN

B5

D-

A7

D+

A6

SHIELD

SH

GND

A1

5.2V

Sheet: /Connector_Signals/
File: connector_signals.kicad_sch

Title:

Size: A4

Date:

KiCad E.D.A. 10.0.5-unknown

Rev:

Id: 7/5