RX - 3 per 1Byte	
Torque_reference	*255 = 100%*
Speed_reference	*255 = 100%*
CMD	
Reset	*x01h*
StandBy	*x02h*
Run	*x04h*
Speed Mode	*x10h*
Torque Mode	*x20h*



TX - 4 per 1Byte	
Torque	*255 = 100%*
Speed	*255 = 100%*
STATUS	
Resume	*x01h*
StandBy	*x02h*
Run	*x04h*
Fault	*x08h*
Speed Mode	*x10h*
Torque Mode	*x20h*
Fault Description	
Overcurrent ph U	*x01h*
Overcurrent ph V	*x02h*
Overcurrent ph W	*x04h*
DClink overvoltage	*x08h*
DClink undervoltage	*x10h*
Overtemperature	*x20h*