

Applications Engineering CQCs MTD as of 14-Jan-14

Entered	Order #	Model	Symptom	Customer	Problem Description	Assigned To	Customer Pain	QTY
1/4/2013	50109305	QCI CON-660-2	Configured /ordered wrong	Siemens Industry, Inc.	Original Order Number50107939CQC CommentsCustomer requested CON-660-2 on a list of parts submitted for review and verification. AE should have corrected to CON-606-2 before quoting. (Dan S.)Customer needs correct cables by 1/7/13. AE DS	Dan Sydney	APPL	4
1/25/2013	50111584	RPL LLG032-00221019	Configured /ordered wrong	HOWARD INDUSTRIES	CQC CommentsAE (JB) configured incorrect wiring, it should have been 3Q05 however it was configured with 3Q01. order 50096492	Jesse Baker	APPL	0
1/25/2013	50111511	RPL LLG032-00221019	Configured /ordered wrong	HOWARD INDUSTRIES	CQC CommentsAE (JB) configured incorrect wiring, it should have been 3Q05 however it was configured with 3Q01. order 50096492	Jesse Baker	APPL	0
3/18/2013	50117052	QCI 042-144-16	Configured /ordered wrong	PROLEC GE INTERNACIONAL S DE RL DE	Original Order Number50115216CQC CommentsThis is a RMA of a RMA, the unit shipped as replacement was wrong due a typo in the previous RMA grid, the unit should been built with 2 SWT and was built with 1, I've attached pictures for reference, the shipme	Janitzio Lazcano	APPL	1
4/3/2013	50118751	QCI LLG042-00225272	Assy incorrect or incomplete	TAMPA ARMATURE WORKS, INC	Original Order Number50111578CQC CommentsCustomer received wrong gage. I created the part number they need (LLG042-00227083). Please ship him these units ASAP.	Mike Guarino	APPL	3
8/26/2013	50133077	RPL CAB-230-1	Configured /ordered wrong	Efacec Power Transformer	CUSTOMER OK'D DEVIATION CABLE, AE DIDN'T KNOW TO ENTER SAME PART # AND FACTORY WOULD USE OTHER CABLE , SO WHEN CUSTOMER RECEIVED CABLE W/O CONNECTOR THIS WAS INCORRECT. AE MG	Mike Guarino	APPL	360

9/4/2013	50133885	QCI	910-011-07	Configured /ordered wrong	EATON CORPORATION (CAD DOLLARS)	Original Order Number50130376CQC CommentsCustomer wanted (2) Horizontal units. I quoted them (2) Vertical units. Please send them (2) VNT-602-1 to make this work for them.	Mike Guarino	APPL	2
9/4/2013	50133773	RPL	092-009-01	Configured /ordered wrong	OTC Services	Original Order Number50131354CQC CommentsVane orientation was incorrectly quoted as Position 1. Customer requested Position 4. Customer was incorrectly informed that this model has an adjustable vane orientation.	Peter Goebel	APPL	2
10/3/2013	50137043	RPL	009-60BE	Configured /ordered wrong	Harty Incorporated USA	Original Order Number50135071CQC CommentsCustomer client didn't approve request to shutdown the transformer to check the mounting style of the cable at the back of the indicator. Customer send a picture of the indicator and requested Qualitrol to help	Mike Guarino	APPL	2
10/7/2013	50137329	QCI	CON000-00007374	Configured /ordered wrong	PROLEC GE INTERNACIONAL S DE RL DE	ORIGINAL ORDER 50135655AE JL 124 – Customer expected twisted/shielded pair for connector but received only the shielded configuration. Configured drawing is incorrect as it shows black/black/white/white.	Janitzio Lazcano	APPL	10
11/6/2013	50140369	QCI	ITM509-00230294	Configured /ordered wrong	HYOSUNG CORPORATION INDUSTRIAL P	Original Order Number50133522CQC CommentsITM509DW configured incorrectly. Missing COV-121-1 and CON-159-1	Daniel Prastawa	APPL	1
11/8/2013	50140569	RPL	CON000-00231895	Configured /ordered wrong	SACRAMENTO MUNICIPAL UTIL	Original Order Number50140176CQC CommentsConfigured the type 1 8Q flying leads instead of the type 2 requested by the customer.Customer complains the color combination on two of the wires is different and we are sending the replacement.CON000-00231	Raihan Ahmed	APPL	1

11/12/2013	50140790	CR	CON-606-5	Configured /ordered wrong	Northern Water	Original Order Number50137408CQC CommentsWrong connector entered by AE PG. Customer needs an 8-pin military style connector and received a 6-pin ANSI style connector.	Peter Goebel	APPL	4
12/16/2013	50143984	QCI	ITM509-00231908	Configured /ordered wrong	SUN CONTINENTAL	Original Order Number50140682CQC CommentsCustomer would like stainless steel tank wall plate.	Daniel Prastawa	APPL	2
12/19/2013	50144429	RPL	ITM509-00228856	Assy incorrect or incomplete	ABB INC.	Original Order Number50134198CQC CommentsThe unit was shipped in a metal enclosure but the enclosure should have been fiberglass.Serial Numbers:50134198-01	Tim Engelbrecht	APPL	1
1/6/2014	50145281	QCI	CON-641-1	Configured /ordered wrong	ALLIANT IES UTILITIES	Original Order Number50142926CQC CommentsAE (JB) quoted CON-641-1 which is a female connector while a male was needed. Drawing shows alignment pins which appear to be a male connection though it is mentioned in the description that is a female.	Jesse Baker	APPL	6
1/8/2014	50145652	QCI	ITM509-00230555	Configured /ordered wrong	HYUNDAI HEAVY IND. CO. LTD.	Original Order Number50136171CQC CommentsCustomer wanted V module of 4to20mA DC but received Unpowered	Daniel Prastawa	APPL	1
				MTD Count	17				
								Total # Units Affected	400