PROJECTLOOP / SYNTHETIC DOCUMENT

Service | Diagnostic report | RO-57004

VIN: WBA3A5C50CF256789

Visited: 2026-09-13

Concern: Intermittent coolant level warning

Finding: Expansion tank sensor fault

Action: Sensor replaced; road test passed

Fictional sample only. Not a real transaction, policy or service record.