



Alonzo Inspections

838 Kipling Ave
South San Francisco, Ca. 94080
Bus Lic #100387 Per Ser 6200

THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT... PLEASE READ CAREFULLY.

Client:	Realtor: S. Huang	Report #:	Huang4232026
Address:		<u>Subject Property</u>	
City/State/Zip:			318 Avalon Ave San Francisco, CA 94112

I/We (Client) hereby request a limited visual inspection of the structure at the above address to be conducted by , (Inspector), for my/our sole use and benefit. I/We warrant that I/We will read the following agreement carefully. I/We understand that I/We are bound by all the terms of this contract. I further warrant that I will read the entire inspection report when I receive it and promptly call the inspector with any questions I may have.

substitute for real estate transfer disclosures which may be required by law.

Whether or not they are concealed, the following ARE OUTSIDE THE SCOPE OF THIS INSPECTION:

- Specific components noted as being excluded on the individual systems inspection forms
- Private water or private sewage systems
- Saunas, steam baths, or fixtures and equipment
- Radio-controlled devices, automatic gates, elevators, lifts, dumbwaiters and thermostatic **or time clock controls**
- Water softener / purifier systems or solar heating systems**
- Furnace heat exchangers, freestanding appliances, security alarms or personal property
- Adequacy or efficiency of any system or component
- Prediction of life expectancy of any item
- Building code or zoning ordinance violations
- Geological stability or soils condition
- Structural stability or engineering analysis
- Termites, pests or other wood destroying organisms
- Asbestos, radon, formaldehyde, lead, water or air quality, electromagnetic radiation or any environmental hazards
- Building value appraisal or cost estimates**
- Condition of detached buildings**
- Pool** or spas bodies and underground piping

(Some of the above items may be included in this inspection for additional fees - check with your inspector)

Your inspector is a home inspection generalist and is not acting as a licensed engineer or expert in any craft or trade.
If your inspector recommends consulting other specialized experts, client must do so at client's expense.

I HAVE READ AND AGREE TO THE ABOVE SCOPE OF INSPECTION.

Client: Realtor: S. Huang

Report #: Huang4232026

THIS IS INTENDED TO BE A LEGALLY BINDING CONTRACT... PLEASE READ CAREFULLY.

ARBITRATION: Any dispute concerning the interpretation of this agreement or arising from this inspection and report, except one for inspection fee payment, shall be resolved informally between the parties or by arbitration conducted in accordance with the rules of the American Arbitration Association except that the parties shall select an arbitrator who is familiar with the home inspection industry. The Arbitrator shall conduct summary judgment motions and enforce full discovery rights as a court would as provided in the Code of Civil Procedure.

USE BY OTHERS: Client promises Inspector that Client has requested this inspection for Client's own use only and will not disclose any part of the inspection report to any other person with these exceptions ONLY: one copy may be provided to the current seller(s) of the property for their use as part of this transaction only, and one copy may be provided to the real estate agent representing Client and/or a bank or other lender for use in Client's transaction only.

ATTORNEY'S FEES: The prevailing party in any dispute arising out of this agreement, the inspection, or report(s) shall be awarded all attorney's fees, arbitrator fees and other related costs.

SEVERABILITY: Client and Inspector agree that should a Court of Competent Jurisdiction determine and declare that any portion of this contract is void, voidable or unenforceable, the remaining provisions and portions shall remain in full force and effect.

DISPUTES: Client understands and agrees that any claim for failure to accurately report the visually discernible conditions at the Subject Property, as limited herein above, shall be made in writing and reported to the Inspector within ten business days of discovery. Client further agrees that, with the exception of emergency conditions, Client or Client's agents, employees or independent contractors, will make no alterations, modifications or repairs to the claimed discrepancy prior to a reinspection by the Inspector. Client understands and agrees that any failure to notify the Inspector as stated above shall constitute a waiver of any and all claims for said failure to accurately report the condition in question.

(Initial)

INSPECTION FEE: \$600.00

Signed: _____ Date: _____

Signed: _____ Date: _____

Signed: Don A. Alonzo *Don Alonzo* Date: 4/23/2026
Inspector**ADDITIONAL SERVICES:**

TOTAL FEES: \$600.00

SUB TOTAL: \$600.00

PAYMENT: _____

TOTAL DUE: \$600.00

KEY TO THE INSPECTION REPORT

Report #: Huang4232026

The "Matrix" Report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

When "**APPEARS SERVICEABLE**" is checked it means that we did not observe conditions that would lead us to believe problems existed with this system or component. The item is capable of being used. Some serviceable items may, however, show wear and tear. Other conditions are checked, if applicable, in the body of the report.

Significantly deficient systems or components will be identified as: Not functional / unsafe / worn / near end of lifespan. When in the inspector's opinion, an item is "significantly deficient", the reason will be checked within the body of the report.

Please read the entire report for all items checked.

Notice: This report contains technical information. If you were not present during this inspection please call the office to arrange for a verbal consultation with your inspector. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents.

KEY TO THE INSPECTION REPORT

***** Items that have an asterisk next to them. This item or component warrants additional attention, repair or monitoring.

(1) Items that have a (1) next to them. The Bracketed Numbers are defined as follows:

(1) Recommended evaluation by a qualified licensed structural engineer / geotechnical engineer.

(2) Recommend further review and repairs as needed by a qualified licensed contractor or specialty tradesman dealing with that item or system.

(3) Recommend further review for the presence of any wood destroying pests or organisms by qualified Pest Inspector.

(4) This item is a safety hazard - correction is needed

(5) Recommend upgrading for safety enhancement. This building may have been constructed before current safety standards were developed.

NOTICE: AN ABRIDGED VERSION OF THIS KEY IS PRINTED AT THE TOP OF EACH REPORT PAGE.

Please read the special "NOTICES" in each section of the report for further information concerning the limitations of this inspection.

If you do not understand how to read this report please contact our office.

I have read and understand the Key to the Matrix Inspection Report.

Client's Initials _____ Representative/Agent's Initials _____

I agree to read the special "NOTICES" in each section of the report for further information concerning the limitations of this inspection.

Client's Initials _____ Representative/Agent's Initials _____

Present During The Inspection ☐ Client ☐ Buyer's Agent ☐ Seller's Agent ☐ Seller

INSPECTOR : Don Alonzo

Inspection Date: Apr/23/2026, Thursday

Start Time: 2:00 pm

Completion Time: 4:00 pm

Weather condition at the time of inspection was Dry

Approximate temperature during inspection: 60.0

Property Information:

The subject property inspected was a (an): Single Family. # of units

Approximate age of building: 1960

Stated by:

Approximate age of roof:

Stated by:

Additions / Alterations to:

Stated by:

NOTICE: It is always wise to check with the building department for permit information, especially if additions or alterations are noted.

IMPORTANT NOTICE TO THIRD PARTIES OR OTHER PURCHASERS: RECEIPT OF THIS REPORT BY ANY PURCHASERS OF THIS PROPERTY OTHER THAN THE PARTY(IES) IDENTIFIED ON THE CONTRACT PAGE #1 IS NOT AUTHORIZED BY THE INSPECTOR. THE INSPECTOR STRONGLY ADVISES AGAINST ANY RELIANCE ON THIS REPORT. WE RECOMMEND THAT YOU RETAIN A QUALIFIED PROFESSIONAL INSPECTOR TO PROVIDE YOU WITH YOUR OWN INSPECTION AND REPORT ON THIS PROPERTY.

GROUNDS

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

1 Driveway☐ N/A☐ Asphalt☒ Concrete☐ N/A

- ☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Eroded Asphalt* ☐ Maintenance* ☐ Sealant needed* ☐ Deterioration* ☐ Evidence of poor drainage*
☐ No cracks found ☐ Common cracks ☐ Major cracks* ☐ Trip hazards* ☐ Surface raised* ☐ Surface settled*

Comments: The driveway appeared to be in serviceable condition at the time of the inspection.

2 SideWalks☐ N/A☒ Concrete☐ Brick☐ Paver / Tile☐ N/A

- ☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ No cracks found ☐ Common cracks ☐ Major cracks* ☐ Trip hazards* ☐ Surface raised* ☐ Surface settled*
☐ Concrete is above* ☐ Evidence of poor drainage*

Comments: The sidewalk appeared to be in serviceable condition at the time of the inspection.

3 Retaining Wall☒ N/A

LOCATION(S):

☐ Concrete☐ Stucco☐

- ☐ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ No cracks found ☐ Common cracks ☐ Major cracks (1) ☐ Moisture penetration* ☐ No drainage openings*

Comments:

4 Patio☐ N/A

LOCATION(S): Entry

☒ Concrete☐ Brick☐

- ☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ No cracks found ☐ Common cracks ☐ Major cracks (1) ☐ Trip hazards* ☐ Surface raised* ☐ Surface settled*
☐ Concrete is above* ☐ Evidence of poor drainage*

Comments: The patio appeared to be in serviceable condition at the time of the inspection.

5 Patio Cover☒ N/A

LOCATION(S):

☐ Earth contact (3)☐ Open Design☐ Covered Roof (refer to Roof Page)*

- ☐ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Attachment to house * ☐ Patio cover lacks
☐ Moisture at ☐ Wood appears

Comments:

6 Decks / Porches☒ N/A☐ WOOD☐ Waterproofed Coating☐ Concrete☐

LOCATION(S): A

B

C

- ☐ **Appears Serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Deck is on grade--unable to inspect* ☐ Piers need ☐ Posts need
☐ Cracks ☐ Moisture ☐ Deck appears unsound (1) (2) ☐ (A) ☐ (B) ☐ (C)
☐ Flashing ☐ Earth-to-wood contact (3) ☐ (A) ☐ (B) ☐ (C)
☐ Porch* ☐ Steps* ☐ Uneven*
☐ Screens* ☐ Panels* ☐ Unable to
☐ Railings are serviceable ☐ N/A ☐ Railing ☐ Railing of

Comments:

7 Fences and Gates☐ N/A☐ NOT INSPECTED☒ Wood☐ Chain Link☐

- ☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Posts are ☐ Blocks are ☐ Boards are
☐ No cracks ☐ Common cracks ☐ Major cracks (2) ☐ Fence height at
☐ Gate(s) need ☐ Self closing device is ☐ Post rusted & leaning*

Comments: The fencing appeared to be in serviceable condition at the time of the inspection.

EXTERIOR

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

8 Exterior Stairs

☐ N/A

Type: Terrazzo

Location: A Front

B

C

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Moisture ☐ Uneven ☐ Openings in rails too large (5)
☒ Railings serviceable ☐ Railings

Comments: The exterior stairs appeared to be in serviceable condition at the time of the inspection.

9 Exterior Walls

☐ N/AStructure: ☒ WOOD FRAME

Wall Covering is: Stucco

Vinyl

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ No cracks found ☐ Common cracks ☐ Major cracks (1) ☐ Cracks / openings need repair (2) ☐ Soil contact *(3)
☐ Moisture stains/damage ☐ Damaged ☐ Nailing defects * ☐

Comments: The exterior walls appeared to be in serviceable condition at the time of the inspection.

Notice: Wall insulation type and value is not verified* UFFI insulation or hazard are not identified* Conditions inside the wall cannot be judged* Lead paint testing is not performed*

10 Trim

☐ N/A☒ WOOD ☐ METAL ☐ VINYL ☐

- ☒ Eaves, soffits, fascia & trim appear serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*
☒ Moisture stains at Gargae Door trim(3) ☐ Not fully visible* ☐ N/A
☐ Flashings / Trim : ☐ Not visible at

Comments: Moisture damage were noted rear exit door at the at the time of the inspection. (2) (3)

11 Chimney(s)

☐ N/A

Location: A Living Room

B

C

D

- Material: A Metal B C D ☒ METAL FLUE ☐ WOOD FRAME
☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Chimney / brick / mortar is: ☐ Settlement (2) ☐ Flashing is
☐ Spark screen present ☐ Spark screen: ☐ Raincap / screen recommended *
☐ Cracks/separations/sealing needed at ☐ Unlined flue (2) ☐ Cracks in chimney cap *
☐ Ash dump / door is: ☐ Damage / deterioration / defect *

Comments: The chimney appeared to be in serviceable condition at the time of the inspection.

Notice: The interior of the flue was not inspected at this time. We recommend that you retain a qualified chimney sweep to clean and evaluate the flue *

12 Sprinklers

☒ N/A☐ Not inspected* ☐ Non operational (2) ☐ Control box location

- ☐ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Valve ☐ Head ☐ Line ☐ Anti-siphon valves needed *
☐ Adjust spray away from ☐ Areas of inadequate spray coverage * ☐ Adjust heads *

Comments:

Notice: Underground pipes cannot be judged for breaks or possible root intrusions. Association-maintained systems are not tested. Grove systems are not tested.*

13 Hose Faucets

☐ N/A☐ Faucets are

- ☒ Appears serviceable ☐ Some inoperative / corroded (2) ☐ Leaks (2) ☐ Missing handle(s)* ☐ Broken handle(s)*

Comments: The hose faucets appeared to be in serviceable condition at the time of the inspection.

14 Gutters & Downspouts

☐ N/A☐ Full☒ Partial☐ None Installed

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Drains blocked* ☐ Debris filled* ☐ Gutters / downspouts:
☐ Add gutters & downspouts for drainage* ☐ Add splashblocks for drainage* ☐ Route downspouts away from building*
☐ Roof / gutters not draining properly* ☐ No secondary drain(s) on roof (2) ☐ Subsurface drains not tested*

Comments: The gutter system appeared to be in serviceable condition at the time of the inspection.

Notice: Gutters and subsurface drains are not water tested for leakage or blockage.* Regular maintenance of drainage systems is required to avoid water problems at the roof and foundation.*

EXTERIOR PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang

Property: 318 Avalon Ave

Date: 4/23/2026

San Francisco, CA 94112

Picture 7



Refer to exterior #10 trim:
Moisture damage were noted rear exit door at the at the
time of the inspection. (2) (3)

Picture 8



Refer to exterior #10 trim:
Moisture damage were noted rear exit door at the at the
time of the inspection. (2) (3)

Picture 9



Refer to exterior #10 trim:
Moisture damage were noted rear exit door at the at the
time of the inspection. (2) (3)

Picture 10



Refer to exterior #10 trim:
Moisture damage were noted rear exit door at the at the
time of the inspection. (2) (3)

FOUNDATION

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

15 Grading ☐ N/A ☐ Level Site ☒ Slope Minor ☐ Moderate ☐ Steep (1) ☐ Stairstepped ☐ Banks

- ☒ Drainage of site/slope of soil at foundation is proper based upon visual observation ☐ Not fully visible*
- ☐ Improper soil slope toward foundation* ☐ Soil / pavement is high at foundation* ☐ Earth-to-wood contact visible* (3)
- ☐ Plants touch ☐ Trees planted close to structure * ☐ Overgrown landscaping*
- ☐ Surface drains noted, not tested - underground pipes cannot be judged* ☐ Signs of poor drainage / erosion*

Comments: Drainage of the site appeared to be in serviceable condition at the time of the inspection.

Notice: This inspection does not include geological conditions or site stability information. For information concerning these conditions, a geologist or soils engineer should be consulted.

☐ 16 Slab-on-grade ☐ 17 Crawlspace ☒ 18 Basement ☐ N/A

- ☒ Foundation: ☒ Poured concrete ☐ Masonry block ☐ Brick ☐ Stone ☐ Piers ☐ Wood ☐ Not visible ☐ None
- ☒ Columns: ☐ Concrete ☐ Steel ☒ Wood ☐ Masonry Block ☐ Brick ☐ Not visible ☐ None
- ☐ Entered crawl space ☐ No access* ☐ Partial access* ☐ Viewed from access opening only*
- ☐ Door / Cover: OK ☐ Damaged* ☐ Missing* ☐ Crawlspace ☐ Basement
- Foundations:** ☐ Visible ☐ Partially visible* ☐ Not visible at*

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
- ☐ No cracks found ☐ Further evaluation needed (2) ☐
- ☐ No moisture present ☐ Exposed footing*
- ☐ Unable to inspect
- ☐ Slab not visible due to carpet and floor covering-recommend further evaluation by removal of the floor covering due to:
- ☐ Cracks found* ☐ Uneven areas in flooring* ☐ Unusual cracks on interior walls* ☐ Unusual cracks on exterior walls*

Ventilation: ☐ Serviceable ☒ N/A ☐ Vents

Comments: The concrete perimeter and post framing was serviceable. Anchor bolts installed. No readily visible problems were found at the time of the inspection.

Notice: All slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. The inspector will, at additional cost, reinspect, provided the client removes floor covering and releases the inspector from damage caused by this process. Floor coverings are not removed during this inspection.*

Floor Construction: ☒ JOISTS ☐ TRUSSES ☒ CONCRETE ☐ NOT VISIBLE ☐ N/A

Wood Frame: ☐ N/A ☒ CONVENTIONAL WOOD FRAMING ☐ TRUSS ☐ Other

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
- ☐ Framing is ☐ Missing framing ☐ Moisture
- ☐ Damaged ☐ Missing ☐ Earth-to-wood contact (2) (3)
- ☐ Joists ☐ Beams ☐ Post ☐ Columns ☐ Debris under house*
- ☐ Concrete floors: ☐ improper slope* ☐ cracked* ☐ deteriorated* ☐ settled(1) ☐ Evidence of
- ☒ Anchor bolts installed ☒ Shear installed ☐ No anchor bolts (1) ☐ No shear panels (1) ☐ Bolts not visible*
- ☐ Probing where deterioration is suspected revealed: ☐ Engineer recommended (1)
- ☐ Insulation

VAPOR RETARDER ☒ N/A ☐ Installed ☐ Not installed* ☐ Not visible* ☐ Loose* ☐ Installed incorrectly*

SUMP PUMP ☒ N/A ☐ Serviceable ☐ Not functional* ☐ Pump not tested* ☐ Sump pump needed*

Comments:

BASEMENT STAIRS ☒ N/A ☐ Serviceable ☐ Uneven rise(2)(4) ☐ Uneven run(2)(4) ☐ loose step(s) (2)(4)

☐ Railings ☐ Stairs too steep (2)(4)(5) ☐ Ceiling is

Comments: N/A

Notice: The inspector does not determine the effectiveness of any system installed to control or remove suspected hazardous substances* No engineering is performed during this inspection *

FOUNDATION PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang

Property: 318 Avalon Ave

Date: 4/23/2026

San Francisco, CA 94112

Picture 13



Picture 14



Refer to foundation #18 Basement:

The concrete perimeter and post framing was serviceable. Anchor bolts installed. No readily visible problems were found at the time of the inspection.

Refer to foundation #18 Basement:

The concrete perimeter and post framing was serviceable. Anchor bolts installed. No readily visible problems were found at the time of the inspection.

Picture 15



Refer to foundation #18 Basement:

The concrete perimeter and post framing was serviceable. Anchor bolts installed. No readily visible problems were found at the time of the inspection.

ROOF

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
(2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
(3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

Roof style: **Main Roof Flat Slope** **Facade Roof Mansard**
How inspected: ☐ Walked ☐ Viewed from ladder* ☐ Viewed from ground* ☐ With binoculars* ☐ Inspection is limited*
☐ Not fully visible due to: ☐ Height ☐ Weather ☐ Snow ☐ Type ☐ Debris ☐ Drone shot

19 Main Roof ☐ N/A **Roof Covering is:** **Tar and Gravel** # of layers:
☒ **Appears serviceable/within useful life** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*(2) ☐ Not fully visible*
☐ Typical maintenance recommended. This usually consists of repair/replacement of damaged/missing ridge and other shakes/shingles. This maintenance should help ensure the water tightness of the building and be performed on a regular basis.*
☒ General condition favorable with signs of weathering and aging-regular maintenance and inspection advised.*
☐ Roof covering has ☐ Moisture stained / damage*
☐ Weathering* ☐ Aging* ☐ Burnt through (2) ☐ Cracking* ☐ Holes/opening (2) ☐ Exposed (2) ☐ Deteriorated membrane (2)
☐ Loose ☐ Displaced ☐ Damaged ☐ Missing: ☐ Pitch appears insufficient (2) ☐ Moss covered*
☐ Roof material appears to be improperly installed (2) ☐ Fasteners are (2)
☐ Roof appears to be ☐ Evidence of prior patching / repairs (2)
Comments: The general condition of the Tar and Gravel roof appears to be in serviceable condition with signs of weathering and aging. We recommend regular maintenance and inspection.

20 Facade Roof ☐ N/A **Roof Covering is:** **Asphalt Composition Shingle** # of layers: 1
☒ **Appears serviceable/within useful life** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*(2) ☐ Not fully visible*
☐ Typical maintenance recommended. This usually consists of covering exposed/bare with additional coating/aggregate material. Repair of open seams, cracks in flashings, deteriorated roof coverings, etc. *
☐ Loose ☐ Displaced ☐ Damaged ☐ Missing ☐ Fasteners (2) ☐ Dented ☐ Rusted ☐ Deteriorated paint (2)
☐ Roof material appears improperly installed (2) ☐ Prior repairs (2) ☐ Insufficient Pitch(2) ☐ Moss covered*
☐ Holes/openings(2) ☐ Exposed(2) ☐ Deteriorated membrane(2)
Comments: The secondary Asphalt Composition Shingle facade roof covering appears to be in serviceable condition.

Notice: Roofs of this material are often not walked on to avoid causing damage. Not all tiles/slates are checked for attachment.* Inspection is limited* Cracks tiles may not be noticable or visible. (*)

21 ☒ N/A **Roof Covering is:** # of layers:
☐ **Appears serviceable/within useful life** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*(2) ☐ Not fully visible*
☐ Typical maintenance recommended. This usually consists of covering exposed/bare with additional coating/aggregate material. Repair of open seams, cracks in flashings, deteriorated roof coverings, etc. *
☐ Excessive damage (2) ☐ Excessive deterioration (2) ☐ Roof material appears to be improperly installed (2)
☐ Blistering* ☐ Cracking* ☐ Alligatoring* ☐ Open seams (2) ☐ Moss covered (2) ☐ Deteriorated surface (2)
☐ Evidence of ☐ Bare areas exposed to the sun (2) ☐ Fasteners
☐ Roof appears to be ☐ Evidence of prior patching / repairs (2)
Comments:

Roof Notes ☐ **NOTICE:**

Comments:

Notice: The report is an opinion of the general quality and condition of the roof.* The Inspector cannot, and does not, offer an opinion or warranty and to whether the roof has leaked in the past, or may be subject to future leakage. Notice: The report is an opinion of the general quality and condition of the roof.*

22 Exposed Flashings ☐ N/A ☒ **Flashings appears serviceable** ☐ N/A
☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*(2) ☐ Not fully visible*
Separation (s) / improper at: ☐ Roof* ☐ Wall* ☐ Drip edge* ☐ Vent Pipes* ☐ Skylight* ☐ Other *
☒ **Vent caps appear serviceable** ☐ Needs repair* ☐ Missing caps* ☐ Rusty flashing* ☐ Mastic covered*
☐ Damaged flashing* ☐ Improper flashing a ☐ No visible flashing at:
☒ **Skylight(s) appear serviceable** ☐ Cracked (2) ☐ Damaged (2) ☐ Defect (2) ☐ Non professional skylight*
Comments:

Notice: Determining the presence of asbestos or hazardous materials is beyond the scope of this inspection.* Roofs, skylights and flashing are not water tested for leaks.* Notice: Tenting a home for fumigation may cause damage to roofs -- recommend reinspection for damage after tenting is completed.*

ROOF PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang
Date: 4/23/2026

Property: 318 Avalon Ave
San Francisco, CA 94112

Picture 19



Picture 20



Refer to roof #19 main roof:

The general condition of the Tar and Gravel roof appears to be in serviceable condition with signs of weathering and aging. We recommend regular maintenance and inspection.

Refer to roof #19 main roof:

The general condition of the Tar and Gravel roof appears to be in serviceable condition with signs of weathering and aging. We recommend regular maintenance and inspection.

Picture 21



Refer to roof #20 Facade roof:

The secondary Asphalt Composition Shingle facade roof covering appears to be in serviceable condition.

PLUMBING

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

23 Main Line ☐ N/A **Main pipe is Copper** **Size: 1"** **Pressure: 80 PSI** ☐ AM ☒ PM
☐ Pressure is above 80 psi - recommend:
☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☒ Main valve location: in Garage ☐ Not located* ☐ Operational ☐ Not operational (2) ☐ Not inspected*
☐ Handle is ☐ Excessive corrosion on valve (2) ☐ Copper pipe not protected from concrete*
☐ Water softener installed (water condition/quality is not tested*) ☐ Leaks at main valve (2) ☐ Leaks at water conditioner (2)

Comments: The main line appeared to be in serviceable condition at the time of the inspection.

24 Supply Lines ☐ N/A **Supply lines are Copper**
☒ **Appear serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Supply pipes show ☐ Leaking noted at:
☐ Water flow appears serviceable ☐ Noise in pipes (2)
☐ Pipes lack support at: ☐ Cross connection(s) present at: ☐ Evidence of
☐ Copper and galvanized pipe contact visible (2) Insulated: ☐ N/A ☐ Yes ☐ No

Comments: The supply lines appeared to be in serviceable condition at the time of inspection.

Notice: Underground pipes or pipes inside walls cannot be judged for size, leaks or corrosion.* Water quality testing or testing for hazards such as lead is not part of this inspection.* Notice: Be advised that some "Polybutylene" plastic piping systems have experienced documented problems.

25 Waste Lines ☐ N/A **Waste lines are Cast Iron**
☒ **Appear serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Waste pipes show ☐ Pipes lack proper support at:
☐ Plumbing Vents & Traps are serviceable ☐ All vents/traps not fully visible* ☒ Leaking noted at: Bathtub drainline
☐ Insufficient fall for adequate drainage (2) ☐ Open waste line (2) ☐ Trap

Comments: The bathtub waste lines were actively leaking at the time of inspection. (2)

Notice: City sewer service, septic systems and all underground pipes are not a part of this inspection. Future drainage performance is also not determined.* Be advised that some "ABS" plastic piping systems have experienced documented problems. Contact the manufacturer or plumbing expert for further information and evaluation.*

26 Fuel System ☐ N/A **Shut Valve Location: Garage** **Fuel type is Gas Meter**
☐ Fuel system is not on for inspection-suggest utilities company light and test all fuel appliances*
☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Pipes not ☐ Pipe is corroded (2) ☐ Pipe is under strain (2)
☐ Improper piping at: ☐ Exposed plastic pipe (2) ☐ Pipe is not 6" above ground (2)
☐ No shutoff valve at: ☐ Improper union at: ☐ Pipes lack proper support (2)

Comments: Fuel system appeared to be in serviceable condition at the time of the inspection.

Notice: Underground piping & fuel tanks cannot be judged. Pipes inside walls or pipes concealed from view cannot be judged and the inspector does not perform tests for gas leaks or pipe size.*

27 Water Heaters ☐ N/A **Location A Garage** **Type Gas** **Capacity 40 Gallons**
Location B **Type** **Capacity**
☒ **Appears serviceable** ☐ Not Functional* ☐ Unsafe* ☒ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ Rust flakes in burner chamber* ☐ Burner flame appears improper (2) ☐ Heater leaks
☒ Water shutoff valve installed (no test) ☐ Corrosion on pipes* ☐ Heater in garage is not on 18" raised platform* (5)
☒ Temperature Pressure Relief Valve overflow pipe is missing (2) ☐ Combustion air
☐ Insufficient clearance to combustible material (2) ☐ Pilot / system off -- could not inspect*
☒ Vent flue piping is serviceable ☐ Vent flue piping
☐ Seismic straps appear serviceable ☒ Seismic straps are improper type* (5) ☐ Thermal blanket
☐ Unit needs a catch pan with an exterior routed drain line* ☐ Recommend protecting heater from physical damage*
☐ Enclosure ☐ Firewall

Comments: Water heater appeared to be serviceable condition at the time of inspection. The water heater had improper seismic straps at the time of the inspection. T P R valve overflow pipe was missing at the time of the inspection. (2)
 MFG 2004

Notice: Estimate of remaining life is not part of this inspection. Solar systems are not part of this inspection. Hot water recalcuating pumps/systems are not part of this inspection.*

PLUMBING PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang
Date: 4/23/2026

Property: 318 Avalon Ave
San Francisco, CA 94112

Picture 25



Picture 26



Refer to plumbing #27 water heater:
Water heater appeared to be serviceable condition at the time of inspection. The water heater had improper seismic straps at the time of the inspection. T P R valve overflow pipe was missing at the time of the inspection.
(2)

Picture of heated water @ 94 degree's

Picture 27



Refer to plumbing #25 wasteline:
The bathtub waste lines were actively leaking at the time of inspection. (2)

HEATING

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
(2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
(3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

28 Description	☐ N/A	Approximate BTU's	Unit A 66,000	Unit B	Unit C
Location A Garage		Location B		Location C Lower livingroom	
Heating Type: Forced air		Heating Type:		Heating Type: Wall	
Fuel Type: Natural gas		Fuel Type:		Fuel Type: Natural gas	
<u>Comments:</u> Heating type is a forced air unit. Fuel type is natural gas.					

Notice: If a fuel burning heater / furnace is located in a bedroom, we recommend evaluation by a qualified heating contractor for safety and air volume requirements.*

29 Condition	☐ N/A	☐ Not inspected*
☒ System(s) appear serviceable	Unit A	☐ Did not respond to normal controls (2)
☐ Not Functional	☐ Unsafe	☐ Worn
☐ System(s)	☐ Near end of lifespan	☐ Damage
	☐ Deterioration	
<u>Comments:</u> The Forced air heating system appeared to be operational at time of inspection.		

Notice: Inspector does not light pilots. If pilots are "OFF", a full inspection is not possible. It is suggested that heating systems be activated and fully inspected PRIOR TO CLOSE OF TRANSACTION. *

30 Venting	☐ N/A	☐ Backventing (2)	☐ Unable to fully inspect vent pipe*
☒ Appears serviceable	☐ Damage (2)	☐ Not accessible*	
☐ Vent lacks clearance from combustibles (2)(4)		☐ Improper vent rise (2)	
☐ Improper materials used for vent pipe (2)(4)		☐ Improper elbow angle (2)	
☐ Soot/Rust on		☐ Defective	
☐ Vent terminates near window/opening (2)(4)			
<u>Comments:</u> The furnace venting appeared to be in serviceable condition at the time of the inspection.			

31 Combustion Air	☐ N/A	☐ Air supply
☒ Appears serviceable	☐ Damage*	☐ Deteriorated*
☐ Combustion and return air sources are too close or mixing (2)	☐ Defects*	
☐ Recommend sealing platform at:		
<u>Comments:</u> The combustion supply air was in serviceable condition at the time of the inspection.		

32 Burners	☐ N/A	☐ Closed system / unable to inspect*
☒ Burner flame appears typical	☐ Unusual flame pattern (2)	
☐ Rust flakes in burn chamber (2)	☐ Damaged	
	☐ Chamber	
<u>Comments:</u> The furnace burner flames appeared to be typical.		

Notice: The inspector is not equipped to thoroughly inspect heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit or other technical procedures.* Some furnaces are designed in such a way that inspection is almost impossible. * Safety devices are not tested by this company. *

33 Distribution	☐ N/A	Type: Ducts & Registers
☒ Appears serviceable	Unit A	☐ Ducts:
☐ Register(s)		☐ Not fully visible*
☐ Zone valve did not operate		☐ Insulation
☐ Radiator inoperative (2)	☐ Radiator cold (2)	☐ Circulating pump
☐ Leaks on radiator (2)	☐ Leaks on convector (2)	☐ Low air volume (2)
	☐ Convector inoperative (2)	☐ Convector cold (2)
	☐ Leaks on fitting (2)	
<u>Comments:</u> The distribution system appeared to be in serviceable condition at the time of inspection.		

Notice: Asbestos materials have been commonly used in heating systems.* Determining the presence of asbestos can ONLY be performed by laboratory testing and is beyond the scope of this inspection.*

HEATING PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang
Date: 4/23/2026

Property: 318 Avalon Ave
San Francisco, CA 94112



Picture 31

Refer to heating #29 condition:
The heating system appeared to be operational at time of inspection.



Picture 32

Picture of heated air @ 109 degree's
Livingroom



Picture 33

Picture of heated air @ 100 degree's
Diningroom /Kitchen



Picture 34

Picture of heated air @ 104 degree's
Bedroom



Picture 35

Picture of heated air @ 104 degree's
Bedroom



Picture 36

Picture of heated air @ 95 degree's
bedroom

HEATING Continued & AIR COOLING

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

34 Normal Controls☐ N/A☐ Unable to inspect* ☐ Utilities off*☒ **Appears serviceable**

Unit A

☐ Thermostat☐ Damage* ☐ Deterioration* ☐ Defects*☐ Controls need☐ Gauges need☐ Switch is☐ Leaks at:☐ Corrosion at:☐ Expansion tankComments: The normal operating controls appeared to be serviceable at the time of the inspection.

Notice: Thermostats are not checked for calibration or timed functions.* Adequacy, efficiency or even heat distribution of the system through the house is not part of this inspection. *

35 Air Filter☐ N/A☐ Missing* ☐ Wrong size* ☐ Unable to inspect*☒ **Appears serviceable**☐ Suggest changing☐ Cleaning filter*☐ No filter hold-down*Comments: The air filters appeared to be in serviceable condition at the time of the inspection.

Notice: Electronic air cleaners, humidifiers and dehumidifiers are beyond the scope of this inspection. * Have these systems evaluated by a qualified individual. *

36 Heating Notes☒ N/A☐ Recommend complete system evaluation (2) ☐ Unable to locate heat in all rooms*☐ Suggest cleaning & servicing☐ Heater makes unusual noise during operation, further evaluation needed (2)☐ High ☐ Low☐ Air leaks at:☐ Condensate lines:☐ Fuel tank leak (2) (4)☐ Undercut doors off carpet*☐ Leakage at:☐ Termination location:Comments: N/A

Notice: Verification of the location or condition of underground fuel storage tanks is not part of this inspection.* Environmental risks, if any, are not included. *

Notice: Asbestos materials have been commonly used in heating systems.* Determining the presence of asbestos can ONLY be performed by laboratory testing and is beyond the scope of this inspection.*

37 Cooler & 38 Air☒ N/A

Location(s) Unit A

B

C

Type:**Power:** ☐ 120volt ☐ 240volt ☐ One speed fan only*☐ **Appears operational**☐ Not Functional*☐ Unsafe*☐ Worn*☐ Near end of lifespan*☐ Not fully visible*☐ Unit makes unusual noise during operation (2)☐ Unit is not level*☐ Pads☐ Unit☐ Float valve☐ Pump☐ Leaking noted*☐ No power - unable to test*☐ Warm air only (2)☐ Air temp below 65 degrees - unable to test system(s)* (operation could cause damage) ☐ One speed fan only*☐ Not level(2) ☐ Makes unusual noise(2)☐ Air temperature differential is incorrect (2)☐ Coil is damaged (2)☐ Recommend servicing system and checking refrigerant level*Comments:**POWER:** ☐ N/A ☐ 120 Volts☐ 240 Volts☐ Electrical disconnect present☐ Gas* (not inspected)☐ No electrical disconnect provided (2)☐ Improper conduit (2)☐ Proper grounding not provided (2)☐ No conduit (2)☐ Junction box ☐ Cover☐ Heat pump auxiliary heat not functional(2)**CONDENSATE:** ☐ N/A☐ Condensate line installed☐ Line not fully visible*☐ Termination location:☐ No trap in line*☐ Condensate lines:**REFRIGERANT LINES:** ☐ N/A☐ Insulation installed on-lines☐ Ice on unit (2)☐ Insulation damaged*☐ Insulation deteriorated*☐ Ice on lines (2)☐ Lines not fully visible☐ Leaks at:☐ Line(s) appear damaged (2)**Comments**☐ N/A

DATA PLATE:

Comments:

Notice: The inspector does not perform pressure tests on coolant systems; therefore no representation is made regarding coolant charge or line integrity. Subjective judgment of system capacity is not part of the inspection.

ELECTRICAL

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

39 Service

☐ N/A☒ Overhead☐ Underground☐ Number of conductors☐ 120V*☒ 240V ☒ 120V☒ AMPS 100☐ AMPS NOT DETERMINED☒ Appears serviceable☐ Defects*☐ Deterioration*☐ Unsafe*☐ Near end of lifespan*☐ Loose connections at☐ Damaged connections at☐ Frayed wires (2) ☐ Improper splices on main wires (2)☐ Improper tap on main wires (2)☐ Conductors too close to☐ Wires touch trees* Contact utility company(4)☒ Ground present ☐ Ground loose at:☐ Ground☐ Ground clamp not visible* ☐ Ground system not visible*☐ More than six breakers with no main shutoff (2)☐ Main disconnect inspected at:☐ No drip loop on service wires (2)Comments: The service appeared to be in serviceable condition at the time of inspection.

40 Main Panel

☐ N/A

#A - Location Garage

☒ Panel rating 100☐ Not verified☐ Power is off at main.No inspection performed* Recommend further evaluation*☒ Appears serviceable☐ Defects*☐ Deterioration*☐ Unsafe*☐ Near end of lifespan*☐ Not accessible*Comments: The main panel appeared to be in serviceable condition at the time of the inspection.

Notice: Six or fewer breakers usually do not require a main breaker, however this may indicate minimal electrical capacity.* If the service amperage is less than 100, upgrade may be needed to operate larger electrical appliances*

41 Conductors

☐ N/A☒ Service Wire: Copper☒ Branch Wire: Copper☒ Wiring Methods: Romex

42 Sub-panel(s)

☒ N/A

B-Location Garage

C-Location

D-Location

Panel >>

☐ is locked-could not inspect.* Further evaluation is needed*

Panel >>

☐ is inaccessible-could not inspect.* Further evaluation is needed*

43 Panel Notes

☐ N/A☒ Wiring Methods:☒ Breakers☐ Fuses☒ Panel(s) appear(s) serviceable☐ Not Functional*☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*☐ Improper wiring (2)(4) at:☐ Breaker is off* at panel:☐ Two wires connected to one breaker (2)(4) at:☐ Signs of☐ Overfusing (fuse/breaker size too large for wire) (2)(4) at:☐ Aluminum wiring noted at the general 120volt circuits(2)(4)☐ Neutral and ground wires connected at sub-panel (2)(4):

(Aluminum connections should be checked by a licensed electrician)

☐ Direct tap☐ Antioxidant not visible on aluminum wire connections*☐ Panel bond is not provided for safety (2)(4) at:☐ Unprotected opening(s) (2)(4) at:☐ Missing 240 volt - handle tie(s) at panel #*:☐ N/A☐ Fused neutral wire(s) (2)(4) at panel:☐ Breakers ☐ Fuses not labeled* at:☐ Electrical system appears outdated by today's standards (2)☐ Opening(s) dead front cover(s) at panel #*(2)Comments: The panel appeared to be in serviceable condition at the time of inspection.

44 Wiring Notes

☐ N/A☒ Sample of switches and outlets tested appear to be serviceable☒ Grounding and polarity of receptacles within 6' of plumbing fixtures appear serviceable☒ Appears serviceable (tested)☐ Three prong outlets did not test properly grounded (2)(4) at:☐ Reverse polarity (2)(4) at:☐ Evidence of☐ Outlet not operational (2)(4) at:☐ Light not operational *(2)(4) at:☐ Outlets ☐ Switches☐ Open neutral (2)(4) at:☐ Not exterior rated☐ Missing cover plates *(2)(4) at:☐ Exposed wiring needs protection (2)(4) at:☐ Damaged cover plates *(2)(4) at:☐ Box cover missing*(4) at:☐ Exposed splices (2)(4) at:☐ Improper wiring (2)(4) at:☐ Extension cord used as wiring (2)(4) at:☒ 'GFCI(s) responded to test ☐ 'GFCI' not operational (2)(4) at:☐ 'GFCI', (a safety device for outlets near water) recommended (5) at:☐ Closet light is subject to damage at:*☐ Closet light is subject to hazard at:*☐ Doorbell worked / none ☐ Not operational (2)☐ FixtureComments: GFCI's responded adequately to test.

ELECTRICAL

Report # Huang4232026

Client: Realtor: S. Huang
Date: 4/23/2026

Property: 318 Avalon Ave
San Francisco, CA 94112



Picture 43

Refer to electrical #40 main panel:
The main panel appeared to be in serviceable condition at the time of the inspection.



Picture 44

Refer to electrical #44 wiring notes:
GFCI's responded adequately to test.
Kitchen



Picture 45

Refer to electrical #44 wiring notes:
GFCI's responded adequately to test.
Bathrooms



Picture 46

Refer to electrical #44 wiring notes:
GFCI's responded adequately to test.
Bathrooms

INTERIOR

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

45 DOORS (Entry) ☐ N/A ☒ **Appears serviceable** ☐ Damage* ☐ Deterioration* ☐ Defects*

☒ **Hardware operational** ☐ Hardware not operational* ☐ Damaged door jamb ☐ Weather stripping damaged/missing*

Comments: The entry doors appeared serviceable at the time of the inspection.

46 & 47 DOORS (Interior & Exterior) ☐ N/A ☐ Several frames are not square - may indicate movement (1)

☒ **Appears serviceable**

☒ **Hardware is operational**

☐ Door(s) rub at:

☐ Damaged at:

☐ Tempered glass

☐ Tracks serviceable

☐ Screen doors not checked*

☐ Not tempered (5)

☐ Deteriorated track(s) a

☐ Screens appear to be servicable.

☐ Damaged jamb* ☐ Needs adjustment at

☐ Missing* ☐ Loose* ☐ Not operational

☐ Door stick at:

☐ Difficult to operate at

☐ Unable to determine tempered glass*

☐ Door won't latch at:

Comments: The interior doors appeared serviceable at the time of the inspection.

48 Windows ☐ N/A **Type: Dual Pane** ☐ Security bars

☒ **Sample tested appears serviceable**

☒ Window dual-glazing was fogged at: Primary bedroom

☒ Window dual-glazing was fogged at: bedroom

☐ Broken *

☐ Window

☐ Stains* ☐ Damage*

☐ Screens

Comments: Dual-glaze windows were fogged at: primary bedroom. (2)

Notice: Determining condition of all insulated windows is not possible due to temperature, weather and lighting variations. Check with owner for further information.

49 Interior Walls ☐ N/A ☒ **Drywall** ☐ Plaster ☐ Paneling ☐ N/A

☒ **General condition serviceable**

☐ Wall

☐ Wall

☐ Wall

☐ Furnishings prevent full inspection-do a careful check on your final walk-through ☐ Recommend evaluation by engineer (1)

Comments: The general condition of the interior walls appeared serviceable at the time of the inspection.

Notice: The condition of walls behind wallpaper, paneling and furnishings cannot be judged.

50 Ceilings ☐ N/A ☒ **Drywall** ☐ Acoustic Spray ☐ Plaster ☐ N/A

☒ **General condition serviceable**

☐ Ceiling(s)

☐ Ceiling(s)

☐ Ceiling(s)

Comments: The general condition of the ceilings appeared serviceable at the time of the inspection.

Notice: Determining whether acoustic sprayed ceilings contain asbestos is beyond the scope of this inspection. For more information please contact the American Lung Association or an asbestos specialist.

51 Floors ☐ N/A ☐ Carpet ☐ Vinyl ☒ **Wood** ☐ Tile ☐

☒ **General condition serviceable**

☐ Damage * ☐ Deterioration *

☐ Cracked tiles at:

☐ Damaged*

☐ Uneven area at:

☐ Furnishings prevent full inspection-do a careful final walk-through* ☐ Loose carpet noted* ☐ Floor squeaks noted*

Comments: The general condition of the floors appeared to be serviceable at the time of the inspection.

Notice: Determining odors or stains is not included! * Floor covering damage / stains may be hidden by furniture.* The condition of wood flooring below carpet is not inspected.*

52 Fireplace(s) ☐ N/A **Location(s) A Living Room B C**

☒ **Appears serviceable**

Type Insert (have checked by removal)* ☐ INSERT (have checked by removal*)

☐ Not Functional*

☐ Unsafe*

☐ Worn*

☐ Near end of lifespan*

☐ Fireplace(s)

☐ Fireplace(s)

☐ Fireplace(s)

☐ **Gas was operational** ☐ N/A

☐ Gas at fireplace

☐ Gas at fireplace

☐ Gas at fireplace

☐ Fans/blowers at fireplace

☐ Remove or block damper open if gas log is used*

Comments: The general condition of the fireplace appears to be in serviceable condition at the time of the inspection.

Notice: Recommend installing safety spacer on damper when gas logs are present* Wood and ashes are not moved for inspection, Recommend clearing debris and further evaluation.*

INTERIOR

Report # Huang4232026

Client: Realtor: S. Huang

Property: 318 Avalon Ave

Date: 4/23/2026

San Francisco, CA 94112

Picture 49



Refer to interior #48 windows:
Dual-glaze windows were fogged at: primary bedroom (2)

INTERIOR Continued

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

53 Interior Features

☒ N/A

- ☐ Interior stairs appear serviceable
☐ Stair handrails appear serviceable
☐ Wet bar faucet appears serviceable
☐ Counter appears serviceable
☐ Plumbing under sink serviceable

Items installed but not inspected:

[Comments:](#)☐ Ceiling fan(s) operational☐ Fan (s)

- ☐ Uneven
☐ Railing is
☐ Faucet is not operational (2)
☐ Damage to
☐ Leaks (2)
☐ Central vacuum ☐ Security system

- ☐ Stairway is
☐ Openings in rails too wide (4)(5)
☐ Faucet leaks (2) ☐ Cold water only
☐ Deterioration to
☐ Improper piping (2) ☐ Icemaker not on
☐ Intercom ☐ N/A

54 Smoke Detector

☐ N/ALocations: A: Hall
C: Bedroom

B: Bedroom

D: Bedroom

- ☒ Smoke detector test button responds
☐ Did not respond to test button*
☐ Couldn't test / no test button*

- ☒ A ☒ B ☒ C ☒ D ☐ Not tested* ☐ A ☐ B ☐ C ☐ D
☐ A ☐ B ☐ C ☐ D ☐ None found (5) ☐ A ☐ B ☐ C ☐ D
☐ Indicator light on ☐ Suggest additional detectors in appropriate locations* (5)

[Comments:](#)

55 Laundry

☐ N/A☒ Garage ☐ Basement ☐ Service Area ☐

- ☒ Piping (water&waste) serviceable ☐ Unable to view / not tested* ☐ Damage* ☐ Deterioration* ☐ Door / jambs*
☒ Electrical outlet grounded (120 Volt) ☐ Unable to test* ☐ Ungrounded* ☐ Not operational (2) ☐ Miswired (2)
☒ 240 volt outlet operational ☐ Inoperative* ☐ No 240 outlet ☐ Not viewed* ☐ Not inspected*
☒ Gas piping appears serviceable ☐ N/A ☐ No gas provided ☐ Unable to view*
☒ Dryer venting provided ☐ Dryer venting not provided* ☐ Dryer vents into attic* ☐ Dryer vents into crawl space*
☒ Laundry sink serviceable ☐ N/A ☐ Damage on sink* ☐ Deterioration on sink* ☐ Sink is loose* ☐ Slow draining*
☒ Plumbing below sink serviceable ☐ Deterioration* ☐ Corrosion* ☐ Improper piping (2) ☐ Leaks (2)
☒ Faucet operational ☐ Deterioration* ☐ Corrosion* ☐ Faucet leaks (2) ☐ Hot/Cold reversed(4)

[Comments:](#) The laundry plumbing appears to be in serviceable condition at the time of the inspection.

Notice: Washing machines and dryers are not moved during this inspection - condition of walls or flooring under these machines cannot be judged.* The inspector does not test washing machine drains or supply valves. * Water supply valves if turned may be subject to leaking. * Washers and dryers are not part of this inspection*

56 Attic

☐ N/A☐ Full ☒ PartialRoof Frame ☒ Truss ☐ Rafter Framing 2x4Ceiling Frame ☒ Truss ☐ Joist Framing 2x6How Inspected: ☐ Entered ☐ Access

Location Bedroom

☐ Inspection limited to view from access*

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☐ No stains visible ☐ Small stains* ☐ Moderate stains (2) ☐ Major stains (2) ☐ Unable to determine leakage*
☐ Sagging framing (1)(2) ☐ Broken framing (1)(2) ☐ Truss(es) ☐ Framing appears undersized* (1)
☒ Vents provided ☐ None* ☐ Blocked* ☐ Minimal* ☐ Poor ventilation* ☐ Missing wind resistant straps(2)
☐ Power ventilator operational ☐ N/A ☐ Not inspected* ☐ Not operational* ☐ Screens
☒ Insulation Type: ☐ No insulation* ☐ Poor coverage* ☐ Compressed* ☐ Wrong side up*
 Approximate depth: ☐ Insulation covers
☐ Air/vapor retarder ☐ N/A ☐ Installed ☐ Vent pipe

[Comments:](#) The attic appeared to be in serviceable condition at the time of the inspection.

Ventilation

☒ N/A☐ Appears serviceable at:☐ Exhaust fan☐ Exhaust fan[Comments:](#)

Notice: Determining the presence of asbestos or other hazardous materials is beyond the scope of this inspection.* Tenting a home for fumigation may cause damage to roofs-recommend reinspection for damage after tenting is completed*

INTERIOR 2 PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang

Property: 318 Avalon Ave

Date: 4/23/2026

San Francisco, CA 94112



Picture 55



Picture 56

GARAGE / Carport

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

GARAGE / CARPORT ☐ N/A ☒ Attached ☐ Detached ☐ Carport ☐ Other

57 Floor ☐ N/A ☒ Appears serviceable ☐ Damage* ☐ Deterioration* ☐ Defects*

☐ No cracks found ☐ Not fully visible* ☐ Major cracks (1) ☐ Possible flammable material on floor*(4)
☐ Floor raised* ☐ Floor settled* ☐ Poor drainage* ☐ N/A

Comments: The garage floor appeared serviceable at the time of the inspection.

58 Firewall / Ceiling ☒ N/A ☐ Not fully visible* ☐ Does not appear fire rated (4) ☐ N/A

☐ Appears serviceable ☐ Moisture stains* ☐ Damage* ☐ N/A
☐ Framing ☐ Exterior: ☐ Holes* ☐ Damage* ☐ Missing wall covering*

Comments:

59 Ventilation ☐ N/A ☒ Appears serviceable ☐ Blocked* ☐ None*
☐ Screens ☐ Window

Comments: The garage ventilation appeared serviceable at the time of the inspection.

60 Door To Interior ☒ N/A ☐ Solid ☐ Rated Door ☐ Hollow Core (non-fire resistive)*

☐ Appears serviceable ☐ Damaged* ☐ Deterioration* ☐ Pet door interrupts integrity of fire door (2)(4)
☐ Bad seal*(4) ☐ Enters bedroom*(4) ☐ Does not latch*(4) ☐ Door lacks threshold* ☐ Door lacks weatherstrip*
☐ Self closer operational ☐ N/A ☐ Closer non-operational* ☐ Closer missing* ☐ Closer needs adjustment*

Comments:

61 Exterior Door ☐ N/A ☒ Appears serviceable ☐ Damaged* ☐ Delaminated* ☐ Needs adjustment*

☐ Lock inoperative* ☐ Damaged door jamb* ☐ Damaged threshold* ☐ Exterior door
☐ Not inspected* ☐ Locked* ☐ Blocked* ☐ Rubs jamb*

Comments: The passage door appeared serviceable at the time of the inspection.

62 Vehicle Door(s) ☐ N/A ☒ Roll Up ☐ Tilt-Up ☐ Sliding ☐ N/A

☒ Appears serviceable ☐ Damage* ☐ Deterioration* ☐ Defects* ☐ Door / jambs* ☐ Moisture stained* ☐ Damaged*
☐ Tension rods loose* ☐ Door warped* ☐ Needs adjustment* ☐ Needs balancing* ☐ Hinges loose* ☐ Damaged*
☐ Safety springs installed ☐ Not safety type springs* (4)(5) ☐ Broken springs (2)(4) ☐ Broken safety wire(2)(4)
☐ Vehicle door(s) are locked - could not test* ☐ Rollers damaged(2) ☐ Tracks damaged(2)

Comments: The vehicle door appeared serviceable at the time of the inspection.

63 Automatic Opener ☐ N/A ☐ Non-operational* ☐ Opener / auto-reverse was not tested*

☒ Appears serviceable # of Units 1 ☐ Unit ☐ Electronic sensor
☒ Automatic reverse operated ☐ Automatic reverse did not operate (2)(4)(5) ☐ Not inspected*

Comments: The automatic opener appeared serviceable at the time of the inspection.

64 Electrical ☐ N/A ☒ Appears serviceable ☐ Damage / deterioration / defects* ☐ Not fully visible*

☐ Improper wiring (2)(4) ☐ Exposed wiring subject to damage *(4) ☐ Extension cords used as permanent wiring (2)(4)
☐ Outlets serviceable ☐ Open ground (2)(4) ☐ Reverse polarity (2)(4) ☐ Improper light fixture wiring (2)(4)
☐ Open splices (2)(4) ☐ Junction boxes missing covers*(4) ☐ 'GFCI' recommended(5) ☐ 'GFCI' defective(2)(4)
☐ Some outlet(s) inaccessible* ☐ Outlet(s) not functional (2) ☐ Loose/damaged outlet(2) ☐ Loose/damaged cover*

Comments:

65 Comments ☒ N/A ☐ Moisture stains on garage ceiling* ☐ Moisture stains on garage wall*

☐ Occupants' belongings block view of entire garage-unable to fully inspect.* Do a careful check on your final walk-through.*

Comments:

KITCHEN

Report # : Huang4232026

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

66 Kitchen Sink(s)☐ N/A☐ Dishes block access to sink, could not inspect*

- ☒ Sink(s) appear(s) serviceable ☐ Minor wear ☐ Heavy wear* ☐ Chipped* ☐ Sink is loose* ☐ Slow draining*
☐ Recommend sealing at sink to counter connection* ☐ No hot water* ☐ Hot & cold water reversed*(4)
☒ Faucet serviceable ☐ Non-operational(2) ☐ Defective(2) ☐ Faucet ☐ Spray wand defective*
☒ Plumbing under sink serviceable ☐ Pipes are ☐ Improper piping (2)
☐ Moisture stains below sink* ☐ Moisture damage below sink* ☐ Restricted view below sink*

67 Kitchen (general)☐ N/ACounters: ☐ Tile ☐ Laminate ☒ Rock☐ Not fully visible*

- ☒ Counters ☒ Floor ☒ Lights ☒ Appear serviceable ☐ Grout* ☐ Caulking* ☐ Handles*
☐ Doors ☐ Drawers ☐ Counter ☐ Other ☐ Minor* ☐ Moderate* ☐ Heavy wear* ☐ Cracks* ☐ Damage*
☐ Minor cracked tile(s)* ☐ Moderate damage* ☐ Heavy damage* ☐ Missing*
☒ Cabinets appear serviceable ☐ Minor wear ☐ Moderate damage* ☐ Heavy wear* ☐ Heavy damage*

Comments: The kitchen sink, cabinet and counter tops appeared to be in serviceable condition at the time of the inspection.

68 Disposal☐ N/A☐ Dishes block access to sink and disposal, could not inspect* ☐ Not fully visible*

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Non operational (2)
☐ Blades appear to be ☐ Unit makes unusual noise* ☐ Splash guard damaged* ☐ Not inspected*
☒ Wiring serviceable ☐ Improper wiring noted (2)(4) ☐ Loose wire clamp at disposal* ☐ Missing wire clamp at disposal*
☐ Switch is in a hazardous location (2)(4) ☐ Exposed wire splices (2)(4) ☐ Missing junction box cover(s)* ☐ Power off*

Comments: Disposal appeared to be in serviceable condition at the time of the inspection.

69 Range / Cooktop☐ N/A

of ovens: 1

☐ Gas☒ Electric☐ Combination☐ Electric Ignition

- ☒ Range / oven appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan*
☐ Upper ☐ Lower ☐ Right ☐ Left ☐ Front ☐ Re ☐ No inspection (power/gas off)*
☐ Free standing oven - not tested* ☐ Ranges / Cooktop not inspected*
☒ Oven door(s) appear(s) serviceable ☐ Lower ☐ Non operational (2)
☒ Door(s) gasket(s) appear(s) serviceable ☐ Damage noted* ☐ Door does not close properly* ☐ Cracked glass (2)
☒ Separate cooktop serviceable ☐ N/A ☐ Damaged gasket(s)* ☐ Clock not tested ☐ Appears non functional*
☐ Gas shutoff valve installed ☐ N/A ☐ Burner did not operate (2) ☐ Element did not operate (2)
☐ Gas shutoff valve not provided (2)(4) ☐ Gas valve is not visible* ☒ Exhaust ventilation appears serviceable

Comments: The range/oven appeared to be in serviceable condition at the time of the inspection.

Notice: Self and/or continuous cleaning operations, clocks, timing devices, lights and thermostat accuracy are not tested during this inspection.* Appliances are not moved.*

70 Dishwasher☐ N/A☐☐ No test (power/water off)*

- ☒ Appears serviceable ☐ Not Functional* ☐ Unsafe* ☐ Worn* ☐ Near end of lifespan* ☐ Not fully visible*
☒ Condition: door, liner & racks serviceable ☐ Rust at ☐ Damage at
☐ Soap dish inoperative* ☐ Washer arm appears frozen (2) ☐ Unit is not secured to cabinets*
☒ Door seals appear serviceable ☐ Deteriorated* ☐ Leaking (2) ☐ Door
DRAIN LINE INSTALLATION: ☐ Air gap device ☐ Hi-loop method ☐ Drain line is improperly installed (2)
☐ Air gap device ☐ None ☐ Improper* ☐ Leaking noted at drain lines ☐ Leaking noted at air gap device*

Comments: The dishwasher appeared to be in serviceable condition at the time of the inspection.

Notice: Determining the adequacy of washing and drying functions of dishwashers is not part of this inspection.*

71 Special Features☒ N/A☐ Special features not inspected*

- ☐ Trash compactor appears serviceable ☐ Non operational (2) ☐ Not inspected* ☐ No Key*
☐ Microwave appears serviceable ☐ Non operational (2) ☐ Not inspected*
☐ Other features/appliances present but not inspected include

Comments:

Notice: Refrigerators, freezers and built-in ice maker are not part of this inspection*

KITCHEN PHOTOS

Report # Huang4232026

Client: Realtor: S. Huang
Date: 4/23/2026

Property: 318 Avalon Ave
San Francisco, CA 94112



Picture 67

Refer to kitchen #69 Range:
The range/oven appeared to be in serviceable condition at the time of the inspection.



Picture 68

Refer to kitchen #69 Range:
The range/oven appeared to be in serviceable condition at the time of the inspection.

BATHROOMS

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

LOCATION: Bath A Main

B

C

D

E

72 Toilet

☒ A ☐ B ☐ C ☐ D ☐ E

Toilet loose at floor* ☐ A ☐ B ☐ C ☐ D ☐ E
 Recommend new wax seal (2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Water runs continually in tank* ☐ A ☐ B ☐ C ☐ D ☐ E
 Does not flush properly* ☐ A ☐ B ☐ C ☐ D ☐ E

Loose toilet tank* ☐ A ☐ B ☐ C ☐ D ☐ E
 Cracked Tank * ☐ A ☐ B ☐ C ☐ D ☐ E
 Rust in Tank * ☐ A ☐ B ☐ C ☐ D ☐ E
 Moisture around toilet (2) ☐ A ☐ B ☐ C ☐ D ☐ E

Comments: The toilets appeared to be serviceable condition in: A

73 Sink

☒ A ☐ B ☐ C ☐ D ☐ E ☐ Hot & cold water reversed*(4)

Sink cracked* ☐ A ☐ B ☐ C ☐ D ☐ E
Faucet appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Sink faucet leaks* ☐ A ☐ B ☐ C ☐ D ☐ E
 Low water volume* ☐ A ☐ B ☐ C ☐ D ☐ E
Drain appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Slow draining* ☐ A ☐ B ☐ C ☐ D ☐ E
 Rust / corroded drain line* ☐ A ☐ B ☐ C ☐ D ☐ E
 Leaking drain line (2) ☐ A ☐ B ☐ C ☐ D ☐ E
Counter & cabinet
Appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Damage to counter* ☐ A ☐ B ☐ C ☐ D ☐ E
 Grout needed at counter* ☐ A ☐ B ☐ C ☐ D ☐ E

Corrosion under sink* ☐ A ☐ B ☐ C ☐ D ☐ E
 Corrosion at sink faucet* ☐ A ☐ B ☐ C ☐ D ☐ E
 Corrosion on supply valve below sink* ☐ A ☐ B ☐ C ☐ D ☐ E
 Sink drain stopper non-functional / missing* ☐ A ☐ B ☐ C ☐ D ☐ E
 Improper drain trap (2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Restricted view below sink* ☐ A ☐ B ☐ C ☐ D ☐ E
 Deterioration to cabinet* ☐ A ☐ B ☐ C ☐ D ☐ E
 Moisture damage below sink* ☐ A ☐ B ☐ C ☐ D ☐ E

Comments: The sink, counter and cabinet appeared to be serviceable condition in: A

74 Vent / Heat

☐ A ☐ B ☐ C ☐ D ☐ E

Comments:

75 Bathtub

☒ A ☐ B ☐ C ☐ D ☐ E

Damage to tub* ☐ A ☐ B ☐ C ☐ D ☐ E
Faucet appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Hot & Cold water reversed(4) ☐ A ☐ B ☐ C ☐ D ☐ E
 Damage at faucet* ☐ A ☐ B ☐ C ☐ D ☐ E
Drain appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Slow draining at bathtub* ☐ A ☐ B ☐ C ☐ D ☐ E

Not applicable to this bathroom ☐ A ☐ B ☐ C ☐ D ☐ E
 Whirlpool not functional (2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Whirlpool not tested(2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Drain stopper missing* ☐ A ☐ B ☐ C ☐ D ☐ E
 Grout needed tub to wall* ☐ A ☐ B ☐ C ☐ D ☐ E

Comments: The bathtub appeared to be serviceable in: A.

76 Shower

☒ A ☐ B ☐ C ☐ D ☐ E

Damage to shower walls* ☐ A ☐ B ☐ C ☐ D ☐ E
 Grout needed at shower walls* ☐ A ☐ B ☐ C ☐ D ☐ E
 Moisture damage to wall (2)(3) ☐ A ☐ B ☐ C ☐ D ☐ E
 Slow draining at shower ☐ A ☐ B ☐ C ☐ D ☐ E
 Leaking at water valve(s) (2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Shower head drip(2) ☐ A ☐ B ☐ C ☐ D ☐ E
Enclosure appears serviceable ☒ A ☐ B ☐ C ☐ D ☐ E
 Glass does not appear to be tempered ☐ A ☐ B ☐ C ☐ D ☐ E
 Broken glass* ☐ A ☐ B ☐ C ☐ D ☐ E
 Caulking needed at enclosure* ☐ A ☐ B ☐ C ☐ D ☐ E

Not applicable to this bathroom ☐ A ☐ B ☐ C ☐ D ☐ E
 Cracked tile(s)* ☐ A ☐ B ☐ C ☐ D ☐ E
 Caulking needed at floor* ☐ A ☐ B ☐ C ☐ D ☐ E
 Floor needs caulking* ☐ A ☐ B ☐ C ☐ D ☐ E
 Low water volume at shower(2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Shower diverter non-functional(2) ☐ A ☐ B ☐ C ☐ D ☐ E
 Unable to determine if glass is tempered* ☐ A ☐ B ☐ C ☐ D ☐ E
 Not applicable to this bathroom ☐ A ☐ B ☐ C ☐ D ☐ E
 Corroded fixtures* ☐ A ☐ B ☐ C ☐ D ☐ E
 Doors difficulty to operate* ☐ A ☐ B ☐ C ☐ D ☐ E
 Damaged enclosure* ☐ A ☐ B ☐ C ☐ D ☐ E

Comments: The shower appeared to be in serviceable condition in: A.

Notice: Determining whether shower pans are watertight is beyond the scope of this inspection.*

REPORT OVERVIEW

Report # : Huang4232026

 The report overview page is provided as a courtesy for quick access to the information within the inspection report. It is not intended as a substitute for reading the inspection report. Items listed below will be discussed further on the corresponding page of the report.

GROUNDS

No recommendations made for the grounds.

EXTERIOR

Please review the following section(s): Trim.

FOUNDATION

No recommendations made for the foundation.

ROOF

Please review the following section(s): Main Roof.

PLUMBING

Please review the following section(s): Waste Lines, Water Heater(s).

HEATING

No recommendations made for this section of heating.

HEATING (Continued) & AIR COOLING

No recommendations made for this section of heating & air cooling.

ELECTRICAL

No recommendations made for the electrical system.

INTERIOR

Please review the following section(s): Windows.

INTERIOR (Continued)

No recommendations made for the interior.

GARAGE

No recommendations made for the garage.

KITCHEN

No recommendations made for the kitchen.

BATHROOM

No recommendations made for the bathroom(s).



Alonzo Inspections
838 Kipling Ave
South San Francisco, Ca. 94080
Bus Lic #100387 Per Ser 6200

Realtor: S. Huang

Invoice

Subject Property:

318 Avalon Ave
San Francisco, CA 94112

Invoice Date: 4/25/2026
Inspection Date: 4/23/2026
Invoice #: 809517
Report #: Huang4232026
Inspector : Don Alonzo

INSPECTION FEES

DESCRIPTION	AMOUNT
INSPECTION FEE:	\$600.00
TOTAL FEES:	<u>\$600.00</u>
SUB TOTAL:	\$600.00
PAYMENT ::	<u> </u>
TOTAL DUE:	\$600.00

Remit payment to:

Alonzo Inspections
838 Kipling Ave
South San Francisco, Ca. 94080
Contact: 415-699-0428