

**Quick Guide**  
Bluetooth 5.0 Inclinometer Sensor

For WT901BLECL, WT9011DCL-BT50  
WTVB01-BT50

1

**Document Center**

**Mobile Connection**

**Preparation**

**Quick pairing**

**Config Menu**

**Recording Data**

**PC Connection**

**How to get the software?**

Scan the QR code, download the WITMOTION PC software, and unzip the files.

For cable connection, you can simply use the cable packed with sensor. If your computer hasn't Bluetooth, you need to buy BLE5.0 Adapter.

7 WT901DCL WT901BLECL Type-C cable BLE Adapter

8

**PC's own Bluetooth Connection**

Step 1. Open the "Bluetooth & other devices" and confirm the Bluetooth "On"

Step 2. Double-hit "WitMotion.exe".(\*new software)

Step 3. Enter the model, baud default 115200 and hit "Search devices"

Step 4. Wait for 30seconds, the data will be displayed.

**Cable Connection**

Step 1. Connect the sensor with offered Type-C cable and turn the switch to ON.

Step 2. Install the driver - CH340, scan the QR code, click to download driver.

Step 5. Hit "Auto-search" button and wait for 30 seconds, data will be displayed.

**\*Adapter Connection**

Please use 2022V software for the Adapter Connection. Scan and download via below QR code.

Step 2. Open the MinilMU.exe application, and choose the right "Port", hit the "Search" button to find the device.

Step 3. Insert adapter into the USB port firstly, turn on the sensor after blue light of adapter flashes.

Step 4. Open the software(MinilMU.exe)

Step 3. Open the device manager, confirm if there is Com ports (COM & LPT) generated.

10

11

12

13

黑色边框不要