MIE231F - PROBABILITY AND STATISTICS

Final Examination - December 21, 2001 Department of Mechanical and Industrial Engineering - University of Toronto - Beno Benhabib

Closed book and notes. You may use only your official aid sheet. You may use any type of band-held calculator. You must answer all questions. The examination is 2 and 1/2 bours long.

- 1. A population of parts are classified as operational versus defective. A statistical analysis of the part population indicates that it has a binomial distribution, where the probability of success (i.e., finding operational parts) is 5%. You are required to purchase a random sample of size n. The sample must have at least 5 operational parts. In order to ensure a 90 to 95% level of confidence in achieving this requirement, what should a minimum acceptable number of parts in the sample be. (i.e., what should minimum n be)? Note that the answer is not unique, since you are given an acceptable range of confidence, as opposed to a single value! [10 points]
- 2. A population of cars have their "life before a major repair" described by a Gamma distribution, where $\alpha=2$ and $\beta=1$.
 - Determine the percentage of the population that is expected not to have a major repair before 5 years. [10 points]
- 3. A population of batteries of Make A is examined via sampling. A random sample of size 40 is examined and found to have the following (normal-distribution) statistics: Mean=12 hours and Variance=1.
 - a) Determine the confidence intervals for the population mean (using estimation theory) for the following levels of confidence: 90%, 95% and 99%. Furthermore, comment on your findings. [10 points]
 - Another producer of batteries. Make B. claims to have "longer lasting batteries" (i.e., its population mean is longer than that of Make A). This claim is to be examined through the following analysis: (μ_A- μ_B). A sample of size 40 is randomly drawn from Population B and the following (normal-distribution) statistics are found: Mean=11.5 hours and Variance=1.
 Determine the confidence intervals for the populations means difference (i.e., μ_A- μ_B) (using estimation theory) for the following levels of confidence: 90%, 95% and 99%. Furthermore, comment on your findings. [10 points]
 - c) What is the maximum level of confidence you can claim in Part (b) of this question above for declaring a winner between the two battery makers. [10 points]
- 4. Two part populations (A and B) are to be compared based on their variances. The population with the <u>lower</u> (normal-distribution) variance value is to be declared the one with the <u>better</u> quality. Two samples are drawn. The following <u>sample</u> statistics are noted: Variance-A is eight times Variance-B, where n_A=5 and n_B=9. Determine with 98% confidence which part population is better. [10 points]
- 5. Three candidates are considered at an election, A, B and C. A small introductory sample of 100 people is polled. 60 favored Candidate A, 20 B and 20 C. A candidate must receive at least 50% of the votes cast to win the election.
 - a) Can the polling company assure Candidate A with 99% confidence that she will win the election? [10 points]
 - b) Candidate A would like more trustworthy polling results and asks the polling company about polling the maximum number of people. However, prior to a decision, she would like first to know what these numbers (i.e., maximum number of people) are for the following corresponding potential error margins: ±2%, ±3% and ±4%, respectively.
 - Determine the three <u>maximum numbers</u> of people to poll; one for each of the above error margins. Note that these numbers do not depend on the proportions of the samples. **[10 points]**
- 6. A lathe is under statistical process control (SPC). Based on historical data, we have the following approximate values for the population mean and variance for cylindrical shafts manufactured on this lathe: 10 and 1, respectively. The operator has been using $z_{\alpha 2}$ =2 SPC control limits.

- a) Under the above production conditions, what percentage of the parts will satisfy the following engineering specifications: 10±3? [10 points]
- b) Discuss in point form how would you notice an out-of-control situation for the above-discussed production of shafts. [10 points]
- 7. You are provided with 100(x,y) data points from an experiment. You are told that the relationship between the two variables is a linear one.

Discuss the use of the following equations for the purpose of a linear-regression of the experimental data:

$$y = a + bx$$
. and

$$\mu_{\rm v} = \alpha + \beta x$$

You may use graphical illustrations in your discussion. [10 points]




Table A.3 Areas Under the Normal Curve

	.00	.01	.02	.03	.04	.05	.46	.97	.00	.09
		0.0003	0,0003	0.0003	0.0003	0.0003	0.0003	0.0003	0.0003	0.0002
- 3.4	0.0003 0.0005	0.0005	0.0005	0.0004	0.0004	0.0004	0.0004	0.0004	0.0004	0.0003
~3_3	0.0007	0.0007	0.0006	0.0006	0.0006	0.0006	0.0006	0.0005	0.0005	0.0005
-3.2	0.0007	0.0009	0.0009	0.0009	0.0008	0.0008	8000.0	0.0008	0.0007	0.0007
-3.1	0.0010	0.0007	0.0013	0.0012	0.0012	0.0011	0.0011	1100.0	0.0010	0.0010
- 3.0					0.0016	0.0016	0.0015	0.0015	0.0014	0.0014
-29	0.0019	0.0018	0.0017	0.0017	0.0016	0.0010	0.0021	0.0021	0.0020	0.0019
-28	0.0026	0.0025	0.0024	0.0023	0.0031	0.0022	0.0029	0.0028	0.0027	0.0026
-27	0.0035	0.0034	0.0033	0.0032	0.0031	0.0040	0.0039	0.0038	0.0037	0.0036
-26	0.0047	0.0045	0.0044	0.0043		0.0040	0.0052	0.0051	0.0049	0.0048
-25	0.0062	0.0060	0.0059	0.0057	0.0055					0.0064
-24	0.0082	0.0080	0.0078	0.0075	0.0073	0.0071	0.0069	0.0068	0.0066	0.0084
-2.3	0.0107	0.0104	0.0102	0.0099	0.0096	0.0094	0.0091	0.0089	0.0087	0.003
-2.2	0.0139	0.0136	0.0132	0.0129	0.0125	0.0122	0.0119	0.0116	0.0113	0.0143
-21	0.0179	0.0174	0.0170	0.0166	0.0162	0.0158	0.0154	0.0150	0.0146	0.0183
-20	0.0228	0.0222	0.0217	0.0212	0.0207	0.0202	0.0197	0.0192	0.0188	
			0.0274	0.0268	0.0262	0.0256	0.0250	0.0244	0.0239	0.0233
-1.9	0.0287	0.0281	0.0274	0.0236	0.0329	0.0322	0.0314	0.0307	0.0301	0.0294
-1.8	0.0359	0.0352	0.0344	0.0330	0.0409	0.0401	0.0392	0.0384	0.0375	0.0367
-1.7	0.0446	0.0436	0.0526	0.0516	0.0505	0.0495	0.0485	0.0475	0.0465	0.0455
-1.6	0.0548	0.0537	0.0526	0.0630	0.0618	0.0606	0.0594	0.0582	0.0571	0.0559
-15	0.0668	0.0655					-	0.0706	0.0694	0.0681
-14	0.0808	0.0793	0.0778	0.0764	0.0749	0.0735	0.0722	0.0853	0.0638	0.0823
-13	0.0968	0.0951	0.0934	0.0918	0.0901	0.0885	0.0869	0.1020	0.1003	0.0985
-12	0.1151	0.1131	0.1112	0.1093	0.1075	0.1056	0.1038	0.1210	0.1190	0.1170
-1.1	0.1357	0.1335	0.1314	0.1292	0.1271	0.1251	0.1230	•	0.1401	0.1379
-1.0	0.1587	0.1562	0.1539	0.1515	0.1492	0.1469	0.1446	0.1423		
	1	0.1814	0.1788	0.1762	0.1736	0.1711	0.1685	0.1660	0.1635	0.1611
-0.9	0.1841	0.1814	0.2061	0.2033	0.2005	0.1977	0.1949	0.1922	0.1894	0.1867
-0.8	0.2119	0.2389	0.2358	0.2327	0.2296	0.2266	0.2236	0.2206	0.2177	0.2148
-0.7	0.2420	0.2709	0.2676	0.2643	0.2611	0.2578	0.2546	0.2514	0.2483	0.2451
-0.6	0.2743		0.3015	0.2981	0.2946	0.2912	0.2877	0.2843	0.2810	0.2776
-0.5	0.3085	0.3050					0.3228	0.3192	0.3156	0.3121
-0.4	0.3446	0.3409	0.3372	0.3336	0.3300	0.3264	0.3594	0.3557	0.3520	0.348
-03	0.3821	0.3783	0.3745	0.3707	0.3669	0.3632	0.3974	0.3936	0_3897	0.385
-0.2	0.4207	0.4168	0.4129	0.4090	0.4052	0.4013	0.4364	0.4325	0.4286	0.424
-0.1	0.4602	0.4562	0,4522	0,4483	0.4443	0.4404		0.4721	0.4681	0.464
-0.0	0.5000	0.4960	0.4920	0.4880	0.4840	0.4801	0.4761	0,4721	V. T	




Table A.6 (continued) Critical Values of the F-Distribution $f_{0.01}(v_1,v_2)$

υ ₁ .										
0,		2	3.	4	5	6	7	8	9	
ι	4052	4999.5	5403	5625	5764	5859	5928	5981	6022	
2	98.50	99.00	99.17	99.25	99.30	99.33	99.36	99.37	99.39	
3	34.12	30.82	29.46	28.71	28.24	27.91	27.67	27.49	27.35	
4	21.20	18.00	16.69	15.98	15.52	15.21	14.98	14.80	14.66	
5	16.26	13.27	12.06	11.39	10.97	10.67	10.46	10.29	10.16	
6	13.75	10.92	9.78	9.15	8.75	8.47	8.26	8.10	7.98	
7	12.25	9.55	8.45	7.85	7.46	7.19	6.99	6.84	6.72	
8	11.26	8.65	7.59	7.01	6.63	6.37	6.18	6.03	5.91	
9	10.56	8.02	6.99	6.42	6.06	5.80	5.61	5.47	5.35	
10	10.04	7.56	6.55	5.99	5.64	5.39	5.20	5.06	4.94	
11	9.65	7.21	6.22	5.67	5.32	5.07	4.89	4.74	4.63	
12	9.33	6.93	5.95	5.41	5.06	4.82	4.64	4.50	4.39	
13	9.07	6.70	j 5.74	5.21	4.86	4.62	4.44	4.30	4.19	
14	8.86	6.51	5.56	5.04	4.69	4.46	4.28	4.14	4.03	
15	8.68	6.36	5.42	4.89	4.56	4.32	4.14	4.00	3.89	
16	8.53	6.23	5.29	4.77	4.44	4.20	4.03	3.89	3.78	
17	8.40	6.11	5.18	4.67	4.34	4.10	3.93	3.79	3.68	
18	8.29	6.01	5.09	4.58	4.25	4.01	3.84	3.71	3.60	
19	8.18	5.93	5.01	0کـ4	4.17	3.94	3.77	3.63	3.52	
20	8.10	5.85	4,94	4.43	4.10	3.87	3.70	3.56	3.46	
21	8.02	5.78	4.87	4.37	4.04	3.81	3.64	3.51	3.40	
22	7.95	5.72	4.82	4.31	3.99	3.76	3.59	3.45	3.35	
23	7.88	5.66	4.76	4.26	3.94	3.71	3.54	3.41	3.30	
24	7.82	5.61	4.72	4.22	3.90	3.67	3.50	3.36	3.26	
25	7.77	5.57	4.68	4.18	3.85	3.63	3.46	3.32	3.22	
26	7.72	5.53	4.64	4.14	3.82	3.59	3.42	3.29	3.18	
27	7 68	5.49	4.60	4.11	3.78	3.56	3.39	3.26	3.15	
28	7.64	5.45	4.57	4.07	3.75	3.53	3.36	3.23	3.12	
29	7.60	5.42	4.54	4.04	3.73	3.50	3.33	3.20	3.09	
30	7.56	5.39	4.51	4.02	3.70	3,47	3.30	3.17	3.07	
40	731	5.18	4.31	3.83	3.51	3.29	3.12	2.99	2.89	
60	7.08	4.98	4.13	3.65	3.34	3.12	2.95	2.82	2.72	
120	6.85	4.79	3.95	3.48	3.17	2.96	2.79	2.66	2.56	
30	6.63	4.61	3.78	3.32	3.02	2.80	2.64	2.51	2.41	