

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Sensor failure on tank level indication

Equipment ID: LB104

Document Number: RCA-017
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-017
Date of RCA	2023-09-12
Reference Event/Incident ID	FE-017
Equipment / Asset	LB104 - LB104 Labeling Machine
Department	Labeling
Facilitator	Employee 14 (Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Sensor failure on tank level indication. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Sensor failure on tank level indication
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Level transmitter wiring fault in humid panel
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Level transmitter wiring fault in humid panel

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Replace pressure sensor, dry terminal block, verify loo	Employee 14	2023-09-19
Update Equipment Manual and PM Schedule	Meera Patil	2023-09-26
Train operators on new procedure	Employee 10	2023-10-03

6. Sign-off

Plant Manager Approval: _____

Date: 2023-09-14