

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Safety (Near Miss)

Slip/trip hazard observed

**Equipment ID: BW102**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-221                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                           |
|-----------------------|---------------------------------|
| Incident ID           | INC-221                         |
| Type                  | Safety (Near Miss)              |
| Date & Time           | 2023-02-03 19:58                |
| Location / Department | Bottle Washing                  |
| Associated Asset      | BW102                           |
| Asset Name            | BW102 Bottle Washing Machine    |
| Reported By           | Employee 10 (Engineer)          |
| Investigator          | Rajesh Kulkarni (Plant Manager) |

## 2. Description of Event

On 2023-02-03 at 19:58, an incident classified as 'Safety (Near Miss)' occurred. The primary observation was: Water pooling on floor near filler.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment BW102 (BW102 Bottle Washing Machine). Refer to equipment manual MAN-BW102-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Install additional floor drain; immediate clean-up.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                                  | Owner            | Target Date | Status      |
|-----------------------------------------------------|------------------|-------------|-------------|
| Install additional floor drain; immediate clean-up. | Rajesh Kulkarni  | 2023-02-10  | Closed      |
| Review and update relevant SOP/RA                   | Employee 10      | 2023-02-17  | In Progress |
| Conduct toolbox talk with shift team                | Shift Supervisor | 2023-02-05  | Closed      |

## 6. Signatures & Closure

Report Prepared By: Employee 10

Date: 2023-02-04

Approved By: Rajesh Kulkarni

Date: 2023-02-05