

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Packaging defect in shrink wrap

Equipment ID: CV102

Document Number: RCA-046
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-046
Date of RCA	2023-10-08
Reference Event/Incident ID	FE-046
Equipment / Asset	CV102 - CV102 Conveyor Belt
Department	Packaging
Facilitator	Employee 2 (Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Packaging defect in shrink wrap. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Packaging defect in shrink wrap
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Shrink tunnel temperature below setpoint
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Shrink tunnel temperature below setpoint
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Inspect heater bank, recalibrate temperature controller	Employee 2	2023-10-15
Update Equipment Manual and PM Schedule	Meera Patil	2023-10-22
Train operators on new procedure	Employee 11	2023-10-29

6. Sign-off

Plant Manager Approval: _____

Date: 2023-10-10