

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## RCA REPORT

### Root Cause Analysis (RCA)

Subject: Power outage stopped packaging line

**Equipment ID: CV104**

|                                                  |
|--------------------------------------------------|
| Document Number: RCA-038                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. RCA Information

### 1.1 Overview

| Parameter                   | Value                       |
|-----------------------------|-----------------------------|
| RCA ID                      | RCA-038                     |
| Date of RCA                 | 2023-01-15                  |
| Reference Event/Incident ID | FE-038                      |
| Equipment / Asset           | CV104 - CV104 Conveyor Belt |
| Department                  | Packaging                   |
| Facilitator                 | Employee 18 (Engineer)      |
| Methodology Used            | 5-Whys                      |

## 2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Power outage stopped packaging line. The immediate impact required corrective action to stabilize the process.

## 3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

| Question                    | Answer                                                  |
|-----------------------------|---------------------------------------------------------|
| Why did the problem happen? | Power outage stopped packaging line                     |
| Why?                        | Because of component/process failure.                   |
| Why did it fail?            | Because it reached its operational limit / was out of s |
| Why was it out of spec?     | Because: Electrical overload caused MCC feeder trip     |
| Why? (Root Cause)           | Systemic gap in maintenance plan or operational procedu |

## 4. Identified Root Cause

Electrical overload caused MCC feeder trip

This has been classified as a systemic failure requiring permanent corrective action.

## 5. Corrective and Preventive Actions (CAPA)

| Action Items                                            | Owner       | Target Date |
|---------------------------------------------------------|-------------|-------------|
| Reset feeder, inspect load balance, test UPS power back | Employee 18 | 2023-01-22  |
| Update Equipment Manual and PM Schedule                 | Employee 1  | 2023-01-29  |
| Train operators on new procedure                        | Employee 6  | 2023-02-05  |

6. Sign-off

Plant Manager Approval: \_\_\_\_\_

Date: 2023-01-17