

Incident Report: High motor current

1. Incident Details

Parameter	Value
Incident ID	INC100
Date of Occurrence	2025-12-10
Equipment	AC203 - Compressor AC203
Location	Plant A, Maintenance (Boiler House - Bay 1)
Severity	MEDIUM
Reporter	Vikram Patil

2. Incident Description & Symptoms

On 2025-12-10, an incident occurred involving Compressor AC203 in the Maintenance department. The equipment experienced high motor current.

Observed Symptoms:

Overcurrent trip

3. Investigation & Actions

Root Cause Analysis:

Intake filter clogged

Immediate & Corrective Actions:

The equipment was secured and LOTO applied. The following corrective action was taken: Replace air intake filter. Total downtime was 3 hours.

4. Lessons Learned & Recommendations

Ensure routine visual inspections capture early degradation.

Investigating Engineer

HSE Manager