

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Bottle overflow at rotary filler

Equipment ID: CM101

Document Number: RCA-018
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-018
Date of RCA	2023-06-17
Reference Event/Incident ID	FE-018
Equipment / Asset	CM101 - CM101 Bottle Capping Machine
Department	Capping
Facilitator	Employee 10 (Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Bottle overflow at rotary filler. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Bottle overflow at rotary filler
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Level sensor calibration drifted after changeo
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Level sensor calibration drifted after changeover
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Calibrate level sensor, validate filling valve shutoff	Employee 10	2023-06-24
Update Equipment Manual and PM Schedule	Employee 11	2023-07-01
Train operators on new procedure	Employee 17	2023-07-08

6. Sign-off

Plant Manager Approval: _____

Date: 2023-06-19