

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Bottle cap missing after capping

Equipment ID: FM104

Document Number: RCA-034
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-034
Date of RCA	2023-04-20
Reference Event/Incident ID	FE-034
Equipment / Asset	FM104 - FM104 Bottle Filling Machine
Department	Filling
Facilitator	Employee 2 (Engineer)
Methodology Used	Fishbone (Ishikawa)

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Bottle cap missing after capping. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Bottle cap missing after capping
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Cap feeder chute jammed due to cap dust buildu
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Cap feeder chute jammed due to cap dust buildup
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Clean cap feeder, inspect chute air jets, verify cap pr	Employee 2	2023-04-27
Update Equipment Manual and PM Schedule	Employee 11	2023-05-04
Train operators on new procedure	Rajesh Kulkarni	2023-05-11

6. Sign-off

Plant Manager Approval: _____

Date: 2023-04-22