

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Machine motor overheating

Equipment ID: WT101

Document Number: RCA-037
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-037
Date of RCA	2023-04-19
Reference Event/Incident ID	FE-037
Equipment / Asset	WT101 - WT101 Water Treatment Unit
Department	Water Treatment
Facilitator	Employee 4 (Engineer)
Methodology Used	5-Whys

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Machine motor overheating. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Machine motor overheating
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Motor bearing wear with insufficient lubricati
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Motor bearing wear with insufficient lubrication

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Lubricate bearings, inspect gearbox, replace motor bear	Employee 4	2023-04-26
Update Equipment Manual and PM Schedule	Employee 14	2023-05-03
Train operators on new procedure	Employee 4	2023-05-10

6. Sign-off

Plant Manager Approval: _____

Date: 2023-04-21