

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Power outage stopped packaging line

Equipment ID: LB103

Document Number: RCA-015
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-015
Date of RCA	2023-08-21
Reference Event/Incident ID	FE-015
Equipment / Asset	LB103 - LB103 Labeling Machine
Department	Labeling
Facilitator	Employee 12 (Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Power outage stopped packaging line. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Power outage stopped packaging line
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Electrical overload caused MCC feeder trip
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Electrical overload caused MCC feeder trip

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Reset feeder, inspect load balance, test UPS power back	Employee 12	2023-08-28
Update Equipment Manual and PM Schedule	Employee 6	2023-09-04
Train operators on new procedure	Employee 15	2023-09-11

6. Sign-off

Plant Manager Approval: _____

Date: 2023-08-23