

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Water leakage from bottle washer

Equipment ID: CH101

Document Number: RCA-019
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-019
Date of RCA	2023-02-01
Reference Event/Incident ID	FE-019
Equipment / Asset	CH101 - CH101 Chiller
Department	Utilities
Facilitator	Employee 6 (Engineer)
Methodology Used	Fishbone (Ishikawa)

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Water leakage from bottle washer. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Water leakage from bottle washer
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Worn EPDM gasket on rinse manifold
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Worn EPDM gasket on rinse manifold

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Replace gasket, pressure test rinse circuit, update was	Employee 6	2023-02-08
Update Equipment Manual and PM Schedule	Employee 9	2023-02-15
Train operators on new procedure	Anita Desai	2023-02-22

6. Sign-off

Plant Manager Approval: _____

Date: 2023-02-03