

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Quality (Product Contamination)

Microbiological failure

**Equipment ID: BL102**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-165                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                              |
|-----------------------|------------------------------------|
| Incident ID           | INC-165                            |
| Type                  | Quality (Product Contamination)    |
| Date & Time           | 2023-08-16 15:52                   |
| Location / Department | Utilities                          |
| Associated Asset      | BL102                              |
| Asset Name            | BL102 Boiler                       |
| Reported By           | Employee 10 (Engineer)             |
| Investigator          | Farah Shaikh (Food Safety Officer) |

## 2. Description of Event

On 2023-08-16 at 15:52, an incident classified as 'Quality (Product Contamination)' occurred. The primary observation was: High yeast count in filler swab.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment BL102 (BL102 Boiler). Refer to equipment manual MAN-BL102-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Perform full double CIP cycle. Increase acid wash temperature by 5°C.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                                      | Owner            | Target Date | Status      |
|---------------------------------------------------------|------------------|-------------|-------------|
| Perform full double CIP cycle. Increase acid wash tempe | Farah Shaikh     | 2023-08-23  | Closed      |
| Review and update relevant SOP/RA                       | Employee 10      | 2023-08-30  | In Progress |
| Conduct toolbox talk with shift team                    | Shift Supervisor | 2023-08-18  | Closed      |

## 6. Signatures & Closure

Report Prepared By: Employee 10

Date: 2023-08-17

Approved By: Farah Shaikh

Date: 2023-08-18