

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Label misalignment on finished bottles

Equipment ID: UPS101

Document Number: RCA-008
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-008
Date of RCA	2023-11-30
Reference Event/Incident ID	FE-008
Equipment / Asset	UPS101 - UPS101 Power Backup
Department	Utilities
Facilitator	Arjun Nair (Maintenance Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Label misalignment on finished bottles. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Label misalignment on finished bottles
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Label roll tension set incorrectly after produ
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Label roll tension set incorrectly after product changeover
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Adjust label roll brake tension and recalibrate registr	Arjun Nair	2023-12-07
Update Equipment Manual and PM Schedule	Employee 11	2023-12-14
Train operators on new procedure	Employee 12	2023-12-21

6. Sign-off

Plant Manager Approval: _____

Date: 2023-12-02