

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Conveyor belt slipping under load

Equipment ID: CH102

Document Number: RCA-051
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-051
Date of RCA	2023-02-02
Reference Event/Incident ID	FE-051
Equipment / Asset	CH102 - CH102 Chiller
Department	Utilities
Facilitator	Employee 12 (Engineer)
Methodology Used	5-Whys

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Conveyor belt slipping under load. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Conveyor belt slipping under load
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Insufficient lubrication and worn drive belt
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Insufficient lubrication and worn drive belt
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Replace conveyor belt, lubricate bearings, check gearbo	Employee 12	2023-02-09
Update Equipment Manual and PM Schedule	Employee 10	2023-02-16
Train operators on new procedure	Employee 19	2023-02-23

6. Sign-off

Plant Manager Approval: _____

Date: 2023-02-04